

D4TXVV

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	163825 KM
<b>File nr. :</b>	1452606	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1EAD169 / VSSZZZ7NZDV506459 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	01/10/2012
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	SEAT / ALHAMBRA	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	54301	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	TECHNICOLOR DELIVERY TECHNOLOGIES BELGIM	<b>Co2:</b>	143g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	7 [x]
<b>Vehicle type :</b>	ALHAMBRA Ecom.Style DPF 136PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	MONOVOLUME	<b>Engine size:</b>	1968
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	7
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	136	<b>kW:</b>	100
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	[x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	H
Rear tyre	215	60	R	16	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT

SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		29.16 EUR

1	2	3	4	5	6	7	8	9	10
29.16	0	0	0	0	0	0	0	0	0
29.16	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
29.16	0	0	<b>29.16</b>
HOG: 0	BG: 2		NA Deprec. 29.16
			0.00%
			<b>TOTAL 29.16</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 27/10/2017 <b>Hour :</b> <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	