

D4VRFK

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	128587 KM
File nr. :	1452640	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EDM421 / VVWZZZ16ZDM628928 /		yr of constructionr :	/
E-File nr. :		First registration :	29/10/2012
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / BEETLE	Fuel type :	DIESEL
Object nr. :	40107	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	INDUSTEEL BELGIUM SA	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	BEETLE Design 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	4
Number of gears:	5	Number of doors:	3
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	[x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	H
Rear tyre	215	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE	HERSTELD
[x]	FRONT MUDGUARD/RIGHT/REAR	DENT	

Interior

[x]	SEAT FL	CARVED
-----	---------	--------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/REAR	DENT	+LAKSCHADE			
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	REAR MUDGUARD/LEFT/FRONT	DENT	+LAKSCHADE			
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	ROOF /FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR	
[x]	FRONT DOOR/RIGHT/REAR	DENT				
	Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR
[x]	BONNET/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
2	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR	
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	

1	2	3	4	5	6	7	8	9	10
211.80	290.08	308.20	789.70	82.80	0	0	0	0	0
105.90	145.04	154.10	394.85	82.80	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
82.80	1599.78	0	1682.58
HOG: 0	BG: 0		NA Deprec. 882.69
			0.00%
			TOTAL 882.69

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 31/10/2017 Hour : 09:53 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	