

www.vabfleetservices.be Date: 30/10/2017 1/4

D4W4CZ

### [X] EFFECTIVE [ ] NOT EXECUTED [ ] COLLECTION [ ] DELIVERY

[x] = Status Modification

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 158838 KM File nr. : Mileage start / arrival: 1452652 0 / 0Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: DD8022 / WVWZZZ7NZDV000776 / E-File nr. : First registration: 09/07/2012 VFS-nr.: Color: **SILVER** Make + Model : Fuel type : VOLKSWAGEN / SHARAN **DIESEL** Object nr. : Fuel: **Environment Class:** Classification: Customer company: Co2: FERRERO INTERNATIONAL SA g/km Driver : Remote controls: 2 LEATHER Covering: Number keys: 2[x]Vehicle kind: **VEHICLE** Seats (minivan): 5 [x] SHARAN Highline BMT DSG 170PK Aut. Vehicle type: Country registration: **BELGIUM** 

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
нр:	170	kW:	125
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		l	



www.vabfleetservices.be Date: 30/10/2017 2/4

Original registr. number :			Service manual :		
Cert. of reg. / Part 1:			Cert. of conformity :		
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate:			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner:	OK	[x]	Filled up :	0	

## Wheels and tyres: Summer tires

	t tyre r tyre		225	4			50			R R		17 17	Y
		[x]	Width			He	ight			Туре		Rim	Index
Wheel RES:	[x]		Tyre:		OK		/	Rim:				/ Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED / Hubca		/ Hubcap:	
Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	

Remark:

## Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	[x]	Width	Height	Type	Rim	Index
Fron	ıt tyre	0	0	R	0	
Rear	r tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 30/10/2017 3/4

### STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/RIGHT/CENTER DENT

[x] BONNET/CENTER/RIGHT DENT

#### STATUS: NOT ACCEPTABLE

#### Bodywork \& windows

[X] FRONT DOOR/LEFT/REAR OTHER DAMAGES SLECHTE HERSTELLING

Number Code Description Unit price Depr. Total

0 0

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 2		NA Deprec.	0
			0.00%	
			TOTAL	0



www.vabfleetservices.be Date: 30/10/2017 4/4

[x] = Status Modification

Pictures: No CIRCUMST	TANCES		NORMAL CONCLUSION						
Extra Time :	0 min	Waiting time: 0 n Reason:	nin	Towing time : Reason :	0 min				
NOT EXECUTED : Reason :	No	<b>I</b>		<b>I</b>					
Remark :	DCUMENTEN	WORDEN NAGESTUURD [x]							
Prices in EUR w	ithout VAT								
Authorized by customer :			Executed by VAB I	Fleet Services					
Remark authorized c	oustomer :								
Date :	30/10/2017	<b>Hour:</b> 08:41							
Company:									
Executed by VAB Flo Services	eet								
E-Mail :	@								
Signature authorized b	y customer								