

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	35420 KM
<b>File nr. :</b>	1453415	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DXC662 / WVVZZZ1KZDW087025 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	24/09/2012
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE
<b>Make + Model :</b>	VOLKSWAGEN / GOLF	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	37065	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	SECURITAS NV	<b>Co2:</b>	99g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	GOLF BER BlueMotion DPF 105PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1598
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	105	<b>kW:</b>	77
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	4-6/	Rim :		/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE
- [x] REAR DOOR/RIGHT/CENTER DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
4	0 LU =0.00 EUR		211.80 EUR		50 %
					211.80 EUR
[x]	FRONT DOOR/LEFT/REAR	DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
3	0 LU =0.00 EUR		318.35 EUR		50 %
					318.35 EUR
[x]	FRONT MUDGUARD/RIGHT/REAR	OTHER DAMAGES			
	<b>Number Code</b>	<b>Description</b>		<b>Unit price</b>	<b>Depr.</b>
					<b>Total</b>
0	0				
[x]	BONNET/CENTER/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
2	0 LU =0.00 EUR		290.08 EUR		50 %
					290.08 EUR
[x]	FRONT BUMPER/CENTER/LEFT	DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
1	15 LU =72.00 EUR		211.80 EUR		50 %
					283.80 EUR

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
6	0 LU =0.00 EUR		75.00 EUR		50 %
					75.00 EUR

### Others

		RIM FRONT LEFT			
			<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
283.80	290.08	318.35	211.80	285.00	75.00	0	0	0	0
141.90	145.04	159.18	105.90	285.00	37.50	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
285.00	1179.03	0	<b>1464.03</b>
HOG: 0	BG: 0		NA Deprec. 874.52
			0.00%
			<b>TOTAL 874.52</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 30/10/2017 <b>Hour :</b> 14:05 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	