

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	118540 KM
File nr. :	1452981	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DUF404 / YV1FW84A1D1102386 /		yr of constructionr :	/
E-File nr. :		First registration :	29/08/2012
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / V60	Fuel type :	DIESEL
Object nr. :	33737	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	VLAAMSE RADIO- EN TELEVISIEOMROEP	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	V60 D2 Kinetic St/St 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate : OK
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	CONTINENTAL	Tyre :	OK	1.6-2/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	CONTINENTAL	Tyre :	OK	1.6-2/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	CONTINENTAL	Tyre :	OK	1.6-2/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	CONTINENTAL	Tyre :	OK	1.6-2/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	ANDERE	Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	235	45	R	17	W
Rear tyre	235	45	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR THRESHOLD/RIGHT/REAR	DENT	INTERIEUR
	BONNET/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT MUDGUARD/RIGHT/REAR	DENT	
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
				Total
4	0 LU =0.00 EUR	211.80 EUR		50 %
				211.80 EUR
[x]	REAR THRESHOLD/LEFT/REAR	DENT	INTERIEUR	
		Repair paint - LI	New paint - E	Depr.
				Total
3	5 LU =24.00 EUR	0 EUR		50 %
				24.00 EUR
	Number	Code	Description	Unit price
				Depr.
				Total
3	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR
				115.56 EUR
[x]	FRONT THRESHOLD/LEFT/REAR	DENT	INTERIEUR	
		Repair paint - LI	New paint - E	Depr.
				Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR
				63.00 EUR

Interior

	SEAT FL	CUT / TORN		
		Repair paint - LI	New paint - E	Depr.
				Total
1	25 LU =120.00 EUR			50 %
				120.00 EUR

DOOR IN FL		CUT / TORN			
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR			50 %	24.00 EUR

DOOR IN REAR RIGHT		CUT / TORN			
Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intvnl-01	VINYL REPAIR	82.20 EUR	82.20 EUR

Others

RIM FRONT LEFT					
Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR LEFT					
Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT					
Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SEAT UPHOLSTERY LEATHER	240.00 EUR	50 %	240.00 EUR
1	1	UPHOLSTERY DOOR	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
556.20	63.00	139.56	211.80	285.00	0	0	0	0	0
319.20	63.00	127.56	105.90	285.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
545.76	709.80	0	1255.56
HOG: 0	BG: 0		NA Deprec. 900.66
			0.00%
			TOTAL 900.66

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 31/10/2017 Hour : 11:10 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	