

D1PNV2

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	151822 KM
File nr. :	1450133	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EBZ326 / YV1FW31A1D1109768 /		yr of constructionr :	/
E-File nr. :		First registration :	16/10/2012
VFS-nr. :		Color :	BLUE
Make + Model :	VOLVO / V60	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	OUDEGEM PAPIER NV	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V60 D3 Kinetic St/St 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1984
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] CONTINENTAL Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RL : [x] CONTINENTAL Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] CONTINENTAL Tyre : [x] OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] CONTINENTAL Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] CONTINENTAL Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	45	R	17	Y
Rear tyre	235	45	R	17	Y

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	BONNET/CENTER/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)

Interior

[x]	FLOOR FL	CARVED
-----	----------	--------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	DENT				
	Number	Code	Description	Unit price	Depr.	Total
	1	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	ROOF/CENTER/RIGHT	OTHER DAMAGES			INWERKING	
			Repair paint - LI	New paint - E	Depr.	Total
	3	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
	2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
63.00	211.80	481.50	0	0	0	0	0	0	0
63.00	105.90	240.75	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	693.30	0	756.30
HOG: 0	BG: 0		NA Deprec. 409.65
			0.00%
			TOTAL 409.65

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/10/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	