

www.vabfleetservices.be Date: 02/11/2017 1/4

D59Z11

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 148956 KM File nr. : Mileage start / arrival: 0 / 01452959 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FQQ101 / WVWZZZ3CZEE048637 / E-File nr. : First registration: 25/09/2013 VFS-nr.: Color: **GREY** Make + Model : VOLKSWAGEN / PASSAT BREAK Fuel type : **DIESEL** Object nr. : Fuel: 12319 Classification: **Environment Class:** EURO 5 Customer company: Co2: SIEMENS NV 120g/km Driver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: PASSAT VAR Comfortline 140PK Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes				
Variant car:	BREAK	Engine size:	1968				
Gear box :	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	5				
HP:	140	kW:	103				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:	No				
		Use:	Unknown				
General condition:							



www.vabfleetservices.be Date: 02/11/2017 2/4

Original registr. number :	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity:
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest:	Transport licence:
Tax certificate:	Navigation CD/SD/DVD
Fuel card :	Car radio :
Mobile phone kit :	Extinguisher:
	Warning triangle :
First aid kit :	Oil level :
Jack, wheelspanner :	Filled up:

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RES:	[x]		Tyre:		OK		/	Rim:				/ Hubcap:	
		[x]	Width			Н	eight	ĺ		Type		Rim	Index
Fron	t tyre		215				55			R		16	V
Rear	tyre		215				55			R		16	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 02/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR WINDOW/RIGHT SCRATCH WITH PAINT DAMAGE

[x] FRONT MUDGUARD/RIGHT/REAR DENT

[x] FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] BONNET/CENTER/LEFT DENT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	0	0	0	0	0	0	0	0	0
63.00	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
63.00	0	0	63.00
NA Deprec. 63.00		BG: 0	HOG: 0
0.00%			

TOTAL 63.00



02/11/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Extra Time :	0 min	Waiting time: 0 m	in .	Towing time :	0 min
Extra Time:	O IIIII		Reason:		OHIIII
		Reason:		Reason:	
NOT EXECUTED	: No				
Reason:					
Remark :					
Prices in EUR	without VAT				
Authorized by		,	Executed by VAB Fleet Se	rvices	
customer :					
Remark authorized	d customer :				
Date :	02/11/2017	Hour: 11:05			
Company :					
Executed by VAB I Services	Fleet				
E-Mail :	@				
Signature authorized	d by customer				
-		/	+		
	/				
	~				