

www.vabfleetservices.be Date: 27/10/2017 1/4

D3PLLG

[X] EFFECTIVE [] NOT EXECUTED

[X] COLLECTION

[] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	44361 KM
File nr. :	1451721	Mileage start / arrival:	0/0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EAT546 / VF1JZ14A647916	112 /	yr of constructionr :	/
E-File nr. :		First registration :	05/10/2012
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :	48506	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company:	TMVW CVBA	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GR.SCENIC Energ.Privilege 5pl.FAP 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes				
Variant car:		Engine size:	1461				
Gear box :	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	5				
HP:	110	kW:	81				
Fisc HP		Imported vehicle:	No				
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:	No				
		Use:	Unknown				
General condition:							



www.vabfleetservices.be Date: 27/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Door	trmo		205			-	55		D		17	V
Fron	t tyre		205			4	55		R		17	V
		[x]	Width			He	eight	Ì	Type		Rim	Index
Wheel RES:	[x]		Tyre:		OK		/	Rim:		/	Hubcap:	
Wheel RR:	[x]	CONTINEN	TAL Tyre:		OK	[x]	>6 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	CONTINEN	TAL Tyre:	[x]	OK	[x]	>6/	Rim:		/	Hubcap:	
Wheel RL:	[x]	CONTINEN	TAL Tyre:		OK	[x]	>6 /	Rim:		/	Hubcap:	
Wheel FL:	[x]	CONTINEN	TAL Tyre:		OK	[x]	>6 /	Rim:		/	Hubcap:	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 27/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/FRONT DENT

[x] REAR DOOR/RIGHT/FRONT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

REAR MUDGUARD/LEFT/CENTER DENT

_	Number	Code	Description	Unit price	Depr. Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR

[x] WINDSCREEN/RIGHT HOLE/CRACK/TORN HERSTELD

Number Code Description Unit price Depr. Total

0 0

[x]

1	2	3	4	5	6	7	8	9	10
0	63.00	0	0	0	0	0	0	0	0
0	63.00	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
63.00		0	0	63.00
63.00	NA Deprec.		BG: 0	HOG: 0
	0.00%			
63.00	TOTAL			



www.vabfleetservices.be Date: 27/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time: 0 min		Towing time :	0 min
		Reason:		Reason:	
NOT EXECUTED:	No				
Reason:					
Remark :					
Prices in EUR wit	hout VAT				
Authorized by			Executed by VAB Fleet Se	ervices	
customer :					
Remark authorized cu	stomer :				
Date :	27/10/2017	Hour:			
Company:					
Executed by VAB Flee Services	t				
E-Mail :	@				
Signature authorized by	customer				
×					
_					