

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	129708 KM
File nr. :	1454518	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FRF649 / WVWZZZ3CZEE048686 /		yr of constructionr :	/
E-File nr. :		First registration :	01/10/2013
VFS-nr. :		Color :	BLUE D
Make + Model :	VOLKSWAGEN / PASSAT BREAK	Fuel type :	DIESEL
Object nr. :	62329	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SOLVAY CHEMICALS INTERNATIONAL	Co2:	113g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PASSAT VAR Trendline BM 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1: OK	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RL :	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel FR :	MICHELIN	Tyre :	OK	2-4/	Rim :	WHEEL SCRATCHED	Hubcap :
Wheel RR :	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RES:	MICHELIN	Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	BONNET/CENTER/LEFT/FRONT	DENT	HAGEL		
Number	Code	Description	Unit price	Depr.	Total
0	0				

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec.
			0.00%
			TOTAL
			0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 31/10/2017 Hour : 13:22 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	