

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	137611 KM
File nr. :	1450479	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPV308 / WV2ZZZ2KZEX041281 /		yr of constructionr :	/
E-File nr. :		First registration :	18/09/2013
VFS-nr. :		Color :	WHITE
Make + Model :	VOLKSWAGEN / CADDY	Fuel type :	DIESEL
Object nr. :	49744	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Besix SA	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	CADDY LIFE Baseline BM 75PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	4
HP:	75	kW:	55
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	NOK [x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RL :	[x]	GOODYEAR	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :		
Wheel FR :	[x]	GOODYEAR	Tyre :	[x] OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	GOODYEAR	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE		
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	MOTORKAP IN /MARTER	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	193.71 EUR		50 %	193.71 EUR
[x]	REAR LIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	REAR WINDOW STYLE/CENTER/LEFT/UP	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
3	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	REAR MUDGUARD/RIGHT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR

Others

	HUB CAP FR				
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	REAR LIGHT	67.50 EUR	50 %	67.50 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	THIRD STOP LIGHT	9.00 EUR	50 %	9.00 EUR

1	2	3	4	5	6	7	8	9	10
322.65	22.50	33.00	193.71	0	0	0	0	0	0
161.32	11.25	16.50	96.86	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	571.86	0	571.86
HOG: 0	BG: 3		NA Deprec. 285.93
			0.00%
			TOTAL 285.93

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 31/10/2017 Hour : 10:26 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	