

D5ZIK4

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: VERY DIRTY [x]
Owner :		Mileage :	153473 KM
File nr. :	1453545	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GFS065 / W0LPD5EX9EG036739 /		yr of constructionr :	/
E-File nr. :		First registration :	27/01/2014
VFS-nr. :		Color :	BLACK
Make + Model :	OPEL / ASTRA	Fuel type :	DIESEL
Object nr. :	44070	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	LE CARROSSE SA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ASTRA SED ecoFLEX Business 130PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1686
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	/	Rim :		Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :		Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :		Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :		Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	H
Rear tyre	215	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT/RIGHT

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	165.64 EUR		50 %	165.64 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 5	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		72.90 EUR

1	2	3	4	5	6	7	8	9	10
72.90	165.64	0	0	0	0	0	0	0	0
72.90	82.82	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
72.90	165.64	0	238.54
HOG: 0	BG: 0		NA Deprec. 155.72
			0.00%
			TOTAL 155.72

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 02/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	