

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|----------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: DIRTY [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 96414 KM |
| File nr. : | 1453562 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1CKI862 / WDD2042001F830190 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 19/12/2011 |
| VFS-nr. : | | Color : | BLUE D |
| Make + Model : | MERCEDES / C BREAK | Fuel type : | DIESEL |
| Object nr. : | 5001 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | INBEV BELGIUM SA | Co2: | 127g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | C BRE 180 CDI BlueEFF. S&S 120PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 2143 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 120 | kW: | 88 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | |
|------------------------------|--------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | OK [x] | Insurance certificate : | |
| Warning vest : | OK [x] | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | [x] |
| Fuel card : | | Car radio : | OK [x] |
| Mobile phone kit : | | Extinguisher : | OK [x] |
| First aid kit : | OK [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | OK [x] | Oil level : | OK [x] |
| | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|--------------------------------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RES: | [x] | | Tyre : | OK | / | | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 55 | R | 16 | H |
| Rear tyre | 205 | 55 | R | 16 | H |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|----------------------------|--------------------------------|
| [x] | REAR BUMPER/CENTER/RIGHT | SCRATCH WITH PAINT DAMAGE |
| [x] | REAR DOOR/LEFT/Front | SCRATCH WITH PAINT DAMAGE |
| [x] | REAR DOOR/RIGHT/Front | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT DOOR/LEFT/REAR | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT MUDGUARD/LEFT/CENTER | SCRATCH (WITHOUT PAINT DAMAGE) |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| [x] | BONNET/CENTER/RIGHT | OTHER DAMAGES | POLIEREN | | |
|--------|---------------------|---------------|------------|-------|-------|
| Number | Code | Description | Unit price | Depr. | Total |
| 0 | 0 | | | | |

Others

CLEANLINESS INTERIOR

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|--------------------------------------|-------------------|-----------|-----------|
| 1 | I2 | specifiek-per-kwartier-a-vab-rein-03 | CLEANING INTERIOR | 14.58 EUR | 29.16 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|---|---|---|---|---|---|---|---|----|
| 29.16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 29.16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|--------------------|
| 29.16 | 0 | 0 | 29.16 |
| HOG: 0 | BG: 0 | | NA Deprec. 29.16 |
| | | | 0.00% |
| | | | TOTAL 29.16 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 31/10/2017 Hour : 08:43 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |