

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	179479 KM
File nr. :	1453408	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HJK391 / WF3LCBHXHES174753 /		yr of constructionr :	/
E-File nr. :		First registration :	01/08/2014
VFS-nr. :		Color :	BLACK
Make + Model :	PEUGEOT / 308	Fuel type :	DIESEL
Object nr. :	77577	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	DURACELL SOLUTIONS BVBA	Co2:	88g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :		
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	SEMPERIT	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	SEMPERIT	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT		
[x]	ROOF STYLE/REAR/LEFT	DENT		
[x]	ROOF/REAR/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)		
[x]	ROOF STYLE/CENTER/RIGHT	DENT		
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	X2	
[x]	FRONT THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	BINNENKANT	
[x]	FRONT DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
				Total
6	0 LU =0.00 EUR	211.80 EUR		50 %
				211.80 EUR
[x]	REAR MUDGUARD/LEFT/FRONT	DENT		
		Repair paint - LI	New paint - E	Depr.
				Total
5	0 LU =0.00 EUR	308.20 EUR		50 %
				308.20 EUR
[x]	FRONT DOOR/LEFT/FRONT	DENT	X2	
		Number	Code	Description
				Unit price
				Depr.
				Total
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR
				63.00 EUR
		Number	Code	Description
				Unit price
				Depr.
				Total
4	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR
				19.80 EUR
[x]	FRONT DOOR/RIGHT/REAR	DENT		
		Number	Code	Description
				Unit price
				Depr.
				Total
7	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR
				63.00 EUR
		Number	Code	Description
				Unit price
				Depr.
				Total
7	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR
				19.80 EUR

[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Interior

[x]	BOOT LID IN	CARVED			
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4 personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR		45.88 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
8	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
8	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
8	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1 UPHOLSTERY DOOR		90.00 EUR	50 %	90.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1 CHROOM LIJST		100.00 EUR	50 %	100.00 EUR

1	2	3	4	5	6	7	8	9	10
159.88	311.80	290.08	82.80	308.20	211.80	82.80	285.00	0	0
102.88	155.90	145.04	82.80	154.10	105.90	82.80	285.00	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
496.48	1235.88	0	1732.36
HOG: 0	BG: 0		NA Deprec. 1114.42
			0.00%
			TOTAL 1114.42

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 30/10/2017 Hour : 15:05 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	