

D65S4V

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	20756 KM
File nr. :	1453687	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
ZD5254 / WVWZZZ16ZFM800163 /		yr of constructionr :	/
E-File nr. :		First registration :	20/08/2014
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / BEETLE CABRIOLET	Fuel type :	PETROL
Object nr. :	ONBEKEND	Fuel :	
Classification :	B	Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	CABRIOLET	Engine size:	1984
Gear box :	Manueel	Number of places:	4
Number of gears:	6	Number of doors:	2
HP:	211	kW:	155
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x] OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	17	V
Rear tyre	215	55	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 15 LU =72.00 EUR	0 EUR	282.96 EUR	50 %	354.96 EUR

[x] REAR MUDGUARD/LEFT/CENTER HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
1 50 LU =240.00 EUR	0 EUR	484.21 EUR	50 %	724.21 EUR

[x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR	115.56 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FENDER REAR LEFT	705.60 EUR	50 %	705.60 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	REAR BUMPER	411.84 EUR	50 %	411.84 EUR

1	2	3	4	5	6	7	8	9	10
2196.61	115.56	0	0	0	0	0	0	0	0
1098.30	115.56	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	2196.61	0	2312.17
HOG: 0	BG: 2		NA Deprec. 1213.86
			0.00%
			TOTAL 1213.86

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : ORIGINELE DOCUMENTEN WORDEN NAGESTUURD [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 31/10/2017 Hour : 16:40 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	