

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	36957 KM
File nr. :	1451133	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LCE758 / XWBAXX11000035143 /		yr of constructionr :	/
E-File nr. :		First registration :	18/08/2015
VFS-nr. :		Color :	BLUE D
Make + Model :	BMW / X4	Fuel type :	DIESEL
Object nr. :	51994	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	WALLENIUS WILHELMSSEN LOGISTICS BELGIUM	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	[x]	Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	[x] OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]	PIRELLI	Tyre :	OK	/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	245	40	R	20	Y
Rear tyre	275	35	R	20	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/LEFT/CENTER DENT

[x] REAR DOOR/RIGHT/CENTER DENT

[x] FRONT DOOR/LEFT/CENTER DENT X2

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT DOOR/LEFT/REAR DENT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	95.00	0	0	0	0	0	0	0	0
63.00	95.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
158.00	0	0	158.00
HOG: 0	BG: 2		NA Deprec. 158.00
			0.00%
			TOTAL 158.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 24/10/2017 Hour : 12:35 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	