

www.vabfleetservices.be Date: 31/10/2017 1/4

D619LY

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	150812 KM
File nr. :	1453584	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EDX328 / WAUZZZ8P0DA0	051868 /	yr of constructionr :	/
E-File nr. :		First registration :	02/11/2012
VFS-nr. :		Color :	BROWN
Make + Model :	AUDI / A3	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:		Environment Class:	EURO 5
Customer company:	KBC BANK NV	Co2:	102g/km
Driver :		Remote controls:	1
Covering:	LEATHER	Number keys :	1 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	A3 SB TDie Attract.Start/Stop DPF 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			



www.vabfleetservices.be Date: 31/10/2017 2/4

Original registr. number : OK Service manual : OK [x] Cert. of conformity: Cert. of reg. / Part 1: OK Insurance certificate: Cert. of reg. copy / Part 2: OK [x]Warning vest: Transport licence: Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK [x] Mobile phone kit : Extinguisher: Warning triangle: OK [x] Oil level: OK First aid kit : [x] OK Filled up: 0 Jack, wheelspanner : [x]

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	/ Hubcap:
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	4-6 /	Rim:	/ Hubcap:
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	/ Hubcap:
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	4-6 /	Rim:	/ Hubcap:
Wheel RES:	[x]	ANDERE	Tyre:		OK		/	Rim:	/ Hubcap:

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	Н
Rear tyre	195	65	R	15	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FL.	Tyle.	OK	,	Killi .	/ Hubcap :
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 31/10/2017 3/4

Conclusion

Bodywork \& windows

[x] BONNET/CENTER/LEFT/FRONT CHIPS

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR BUMPER/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR MUDGUARD/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

[x] REAR MUDGUARD/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 1		NA Deprec. 0
			0.00%

TOTAL

0



www.vabfleetservices.be Date: 31/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting tir	Waiting time: 0 min			0 min	
		Reason:			Towing time : Reason :		
NOT EXECUTED): No						
Reason:							
Remark :							
Prices in EUR	without VAT						
Authorized by customer :		,		Executed by VAB	Fleet Services		\Box
customer .							
Remark authorized customer :							
Date :	31/10/2017	Hour:	11:41				
Company :							
	Til 4						
Executed by VAB Services	rieet						
E-Mail :	@						
Signature authorize	ed by customer						\dashv
–	•		-	 			\dashv