

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	38601 KM
File nr. :	1456398	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LPD599 / WAUZZZ8V8GA064015 /		yr of constructionr :	/
E-File nr. :		First registration :	03/11/2015
VFS-nr. :		Color :	BLACK
Make + Model :	AUDI / A3 SPORTBACK	Fuel type :	DIESEL
Object nr. :	77993	Fuel :	
Classification :	E	Environment Class:	EURO 6
Customer company :	THE BOSTON CONSULTING GROUP	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RL :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel FR :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RR :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RES:			Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR

[x] REAR LIGHT/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

[x] REAR MUDGUARD/RIGHT/CENTER DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 50 LU =240.00 EUR	0 EUR	322.81 EUR	50 %	562.81 EUR

[x] REAR DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	254.68 EUR		50 %	254.68 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	REAR LIGHT	72.00 EUR	50 %	72.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	FENDER REAR RIGHT	470.40 EUR	50 %	470.40 EUR

1	2	3	4	5	6	7	8	9	10
265.44	1287.89	0	0	0	0	0	0	0	0
132.72	643.94	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1553.33	0	1553.33
HOG: 0	BG: 1		NA Deprec. 776.66
			0.00%
			TOTAL 776.66

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/11/2017 Hour : 14:46 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	