

D7KHVS

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	135182 KM
File nr. :	1454834	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FFM557 / WAUZZZ4G8DN157158 /		yr of constructionr :	/
E-File nr. :		First registration :	14/06/2013
VFS-nr. :		Color :	BLACK
Make + Model :	AUDI / A6	Fuel type :	DIESEL
Object nr. :	58934	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	NYRSTAR BELGIUM NV	Co2:	129g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	A6 BER 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	Yes
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD OK
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RL :	MICHELIN	Tyre :	OK	1.6-2/	Rim :	/	Hubcap :
Wheel FR :	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RR :	MICHELIN	Tyre :	OK	1.6-2/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	[x]	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE	
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	POLIJSTEN
[x]	FRONT DOOR/RIGHT/FRONT	DENT	
[x]	WINDSCREEN/BELOW/LEFT	WINDOW DAMAGE	
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT BUMPER/RIGHT/SIDE	OTHER DAMAGES	MATIG HERSTELD

Interior

[x]	CARPET FL	OTHER DAMAGES
-----	-----------	---------------

Accessories and others

OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT
-----	----------------------------	------

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		97.80 EUR

1	2	3	4	5	6	7	8	9	10
97.80	0	0	0	0	0	0	0	0	0
97.80	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
97.80	0	0	97.80
HOG: 0	BG: 2		NA Deprec. 97.80
			0.00%
			TOTAL 97.80

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 14:22 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	