

www.vabfleetservices.be Date: 14/04/2017 1/4

AU40CQ

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar: KBC REMARKETING Cleanliness: INT: CLEAN [x] EXT: DIRTY [x]

Owner: Mileage: 97822 KM

File nr.: 1388289 Mileage start / arrival: 0 / 0

Reg number / Chassis / Ref: Mileag ref. service: ()

1ELJ017 / WAUZZZ8X1DB069306 / yr of constructionr: /

E-File nr.: First registration: 14/01/2013

VFS-nr.: Color: BLUE D

Make + Model: AUDI / A1 Fuel type: DIESEL

Object nr.: 3115 Fuel:

Classification: Environment Class: EURO 5

Customer company: MEDIABRANDS BELGIUM Co2: 99g/km

Driver: Remote controls: 1

Covering: LEATHER Number keys: 1 [x]Vehicle kind: VEHICLE Seats (minivan): 0

Vehicle type: A1 BER Ambition Start/Stop DPF 105PK Country registration: BELGIUM

VAT over the margin - car: No Metallic paint:

Variant car: Engine size: 1598

Gear box: Manueel Number of places:

Number of gears: 5 Number of doors:

HP: 105 kW: 77

Fisc HP Imported vehicle:

Animals transported: Smoked in vehicle:

Due date vehicle inspection: Extra set of tires:

Use: Unknown

General condition: MMI SCHERM OPENT NIET



www.vabfleetservices.be Date: 14/04/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Winter tires

				1			
Wheel RES	S: [x]		Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR	: [x]	MICHELIN	Tyre:	OK	[x] 2-4/	Rim:	/ Hubcap:
Wheel FR	: [x]	MICHELIN	Tyre: [x] OK	[x] 2-4/	Rim:	/ Hubcap:
Wheel RL	: [x]	MICHELIN	Tyre:	OK	[x] 2-4/	Rim:	/ Hubcap:
Wheel FL:	[x]	MICHELIN	Tyre:	OK	[x] 2-4/	Rim:	/ Hubcap:

 [x]	Width	Height	Type	Rim	Index
Front tyre	215	45	R	16	M+S
Rear tyre	215	45	R	16	M+S

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 14/04/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork	\& wind	ows
----------	---------	-----

[x] BONNET/CENTER/LEFT/FRONT

CHIPS

STATUS: NOT ACCEPTABLE

Interior

[x] CENTER CONSOLE

OTHER DAMAGES

Number Code Description Unit price Depr. Total

0 0

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 1		NA Deprec.	0
			0.00%	
			TOTAL	0



www.vabfleetservices.be Date: 14/04/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES			NORMAL CONCLUSION			
Extra Time :	0 min	Waiting time : Reason :	0 min		Towing time : Reason :	0 min	
NOT EXECUTED : Reason :	No	!					
Remark:	NAVI NIET TE	CONTROLEREN/OPENT NIE	T [x]				
Prices in EUR w	rithout VAT						
Authorized by customer :				Executed by VAB Flee	et Services		
Remark authorized	customer :						
Date :	14/04/2017	Hour: 09:36	5				
Company : Executed by VAB Fl Services	leet						
E-Mail :	@						
Signature authorized	by customer						