

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 104555 KM |
| File nr. : | 1441348 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1DPK652 / WVVZZZ3CZDE515757 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 13/07/2012 |
| VFS-nr. : | | Color : | BROWN D |
| Make + Model : | VOLKSWAGEN / PASSAT CC | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | KBC GROEP NV | Co2: | 120g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | | Seats (minivan) : | 0 |
| Vehicle type : | CC BMT 136PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BERLINE | Engine size: | 1968 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 4 |
| HP: | 136 | kW: | 100 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | |
|------------|-----|-------------|--------|-----|-----|------|-------|-------|----------------------------|----------------------------|
| Wheel FL: | [x] | PIRELLI | Tyre : | OK | [x] | >6/ | Rim : | / | Hubcap : | |
| Wheel RL : | [x] | CONTINENTAL | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED / Hubcap : | |
| Wheel FR : | [x] | PIRELLI | Tyre : | [x] | OK | [x] | >6/ | Rim : | [x] | WHEEL SCRATCHED / Hubcap : |
| Wheel RR : | [x] | CONTINENTAL | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED / Hubcap : | |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 235 | 45 | R | 17 | W |
| Rear tyre | 235 | 45 | R | 17 | W |

Remark : RFT

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | |
|-----|------------------------------|--------------------------------|----------------------|
| [x] | REAR MUDGUARD/RIGHT/FRONT | DENT | |
| [x] | REAR DOOR/LEFT/FRONT | SCRATCH (WITHOUT PAINT DAMAGE) | ONDERAAN = OVBH POL. |
| [x] | ROOF/REAR/LEFT | SCRATCH (WITHOUT PAINT DAMAGE) | POL. |
| [x] | REAR DOOR/RIGHT/CORNER/BELOW | SCRATCH (WITHOUT PAINT DAMAGE) | POL. |
| [x] | REAR DOOR/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE | +KRAS |
| [x] | FRONT DOOR/LEFT/REAR | DENT | |
| [x] | FRONT DOOR/LEFT/CENTER | SCRATCH (WITHOUT PAINT DAMAGE) | ONDERAAN = OVBH POL. |
| [x] | FRONT DOOR/RIGHT/REAR | SCRATCH WITH PAINT DAMAGE | |
| [x] | BONNET/CENTER/LEFT/FRONT | CHIPS | |

Interior

| | | |
|-----|---------|-----------|
| [x] | SEAT FL | SCRATCHED |
|-----|---------|-----------|

Accessories and others

| | | |
|-----|------------------------------|---------------------------|
| [x] | OUTSIDE MIRROR LEFTHAND SIDE | SCRATCH WITH PAINT DAMAGE |
|-----|------------------------------|---------------------------|

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | |
|-----|--------------------------|---------------------------|----------------------|
| [x] | REAR BUMPER/CENTER/RIGHT | SCRATCH WITH PAINT DAMAGE | +LAK GEBARSTEN |
| | | Repair paint - LI | New paint - E |
| | | | Depr. |
| | | | Total |
| 3 | 0 LU =0.00 EUR | 211.80 EUR | 50 % |
| | | | 211.80 EUR |

| | | | |
|-----|---------------------------|---------------------------|----------------------|
| [x] | FRONT BUMPER/RIGHT/CORNER | SCRATCH WITH PAINT DAMAGE | |
| | | Repair paint - LI | New paint - E |
| | | | Depr. |
| | | | Total |
| 2 | I 1 i-vab-sp-01 | SPOTREPAIR | 115.56 EUR |
| | | | 115.56 EUR |

Others

| | | | |
|---|-----------------------|--------------------------|----------------------|
| | | RIM REAR LEFT | |
| | | Repair paint - LI | New paint - E |
| | | | Depr. |
| | | | Total |
| 1 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR |
| | | | 95.00 EUR |

RIM REAR RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 1 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 1 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|---|---|---|---|---|---|----|
| 285.00 | 115.56 | 211.80 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 285.00 | 115.56 | 105.90 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 400.56 | 211.80 | 0 | 612.36 |
| HOG: 0 | BG: 0 | | NA Deprec. 506.46 |
| | | | 0.00% |
| | | | TOTAL 506.46 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : NAVI OK [x] | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 27/09/2017 Hour : 16:24 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |