APPRAISAL

CYEVNC

[X] EFFECTIVE   [ ] NOT EXECUTED   [ ] COLLECTION   [ ] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	46255 KM
File nr. :	1447582	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
GL9621 / WBA4E91060G285832 /		yr of constructionr :	/
E-File nr. :		First registration :	22/10/2015
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / 4 GRAN COUPÉ	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	PWC	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GRAND COUPE 420D	Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	COUPE	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	190	kW:	140
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK			Service manual :			
Cert. of reg. / Part 1:	OK	[x]		Cert. of conformity :	NOK	[x] MISSING/INCOMPLETE	
Cert. of reg. copy / Part 2:	NOK	[x]		Insurance certificate :			
Warning vest :	OK	[x]		Transport licence :			
Tax certificate :				Navigation CD/SD/DVD			
Fuel card :				Car radio :	OK	[x]	
Mobile phone kit :				Extinguisher :	OK	[x]	
				Warning triangle :	OK	[x]	
First aid kit :	OK	[x]		Oil level :	OK	[x]	
Jack, wheelspanner :				Filled up :	0		

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :		OK	[x]	4-6 /	Rim :	/	Hubcap :	
Wheel RL :	[x]	BRIDGESTONE	Tyre :		OK	[x]	4-6 /	Rim :	/	Hubcap :	
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/	Hubcap :	
Wheel RR :	[x]	BRIDGESTONE	Tyre :		OK	[x]	4-6 /	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :		OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	W
Rear tyre	225	50	R	17	W

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

APPRAISAL

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT BUMPER/CENTER/RIGHT   HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	0 EUR		50 %	

	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

[x] FRONT BUMPER/RIGHT   SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FOG LAMP	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
229.56	0	0	0	0	0	0	0	0	0
172.56	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
115.56	114.00	0		**229.56**
HOG: 0	BG: 0		NA Deprec.	172.56
			0.00%	
			TOTAL	**172.56**

APPRAISAL

[x] = Status Modification

Pictures :   No

CIRCUMSTANCES

                UNDER CONDITION - DUSTY VEHICLE

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason :		Reason :	

NOT EXECUTED :	No
Reason :	
Remark :	

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 06/11/2017 **Hour :** 11:39	
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	