

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

|                                     |                        |                                 |                               |
|-------------------------------------|------------------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING        | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: CLEAN [x] |
| <b>Owner :</b>                      |                        | <b>Mileage :</b>                | 165994 KM                     |
| <b>File nr. :</b>                   | 1453343                | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                        | <b>Mileag ref. service :</b>    | 0                             |
| ZN7932 / WBA3D31010J557122 /        |                        | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                        | <b>First registration :</b>     | 16/01/2014                    |
| <b>VFS-nr. :</b>                    |                        | <b>Color :</b>                  | GREY                          |
| <b>Make + Model :</b>               | BMW / 3                | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 |                        | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             |                        | <b>Environment Class:</b>       |                               |
| <b>Customer company :</b>           | SOGETI LUXEMBOURG SA   | <b>Co2:</b>                     | g/km                          |
| <b>Driver :</b>                     |                        | <b>Remote controls:</b>         | 2                             |
| <b>Covering :</b>                   | TISSUE                 | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle kind :</b>               | VEHICLE                | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               | 3 BER 320dA 184PK Aut. | <b>Country registration :</b>   | LUXEMBOURG                    |

|                                     |                   |                            |         |
|-------------------------------------|-------------------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   | No                | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 | BERLINE           | <b>Engine size:</b>        | 1995    |
| <b>Gear box :</b>                   | Automaat algemeen | <b>Number of places:</b>   | 5       |
| <b>Number of gears:</b>             |                   | <b>Number of doors:</b>    | 4       |
| <b>HP:</b>                          | 184               | <b>kW:</b>                 | 135     |
| <b>Fisc HP</b>                      |                   | <b>Imported vehicle:</b>   |         |
| <b>Animals transported:</b>         | No                | <b>Smoked in vehicle:</b>  | No      |
| <b>Due date vehicle inspection:</b> |                   | <b>Extra set of tires:</b> | No      |
|                                     |                   | <b>Use:</b>                | Unknown |

**General condition:**

|                              |        |                         |        |
|------------------------------|--------|-------------------------|--------|
| Original registr. number :   |        | Service manual :        | [x]    |
| Cert. of reg. / Part 1:      | OK [x] | Cert. of conformity :   | OK     |
| Cert. of reg. copy / Part 2: | OK [x] | Insurance certificate : |        |
| Warning vest :               | OK [x] | Transport licence :     |        |
| Tax certificate :            |        | Navigation CD/SD/DVD    |        |
| Fuel card :                  |        | Car radio :             | OK [x] |
| Mobile phone kit :           |        | Extinguisher :          | OK [x] |
| First aid kit :              | OK [x] | Warning triangle :      | OK [x] |
| Jack, wheelspanner :         |        | Oil level :             | OK [x] |
|                              |        | Filled up :             | 0      |

## Wheels and tyres: Summer tires

|            |     |        |        |            |      |       |   |          |
|------------|-----|--------|--------|------------|------|-------|---|----------|
| Wheel FL:  | [x] | DUNLOP | Tyre : | OK [x]     | 2-4/ | Rim : | / | Hubcap : |
| Wheel RL : | [x] | DUNLOP | Tyre : | OK [x]     | 2-4/ | Rim : | / | Hubcap : |
| Wheel FR : | [x] | DUNLOP | Tyre : | [x] OK [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RR : | [x] | DUNLOP | Tyre : | OK [x]     | 2-4/ | Rim : | / | Hubcap : |
| Wheel RES: | [x] | ANDERE | Tyre : | OK         | /    | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225   | 55     | R    | 16  | W     |
| Rear tyre  | 225   | 55     | R    | 16  | W     |

Remark :

## Wheels and tyres:

|            |  |  |        |    |   |       |   |          |
|------------|--|--|--------|----|---|-------|---|----------|
| Wheel FL:  |  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : |  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : |  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : |  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: |  |  | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR DOOR/RIGHT/FRONT DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

| [x] | BONNET/CENTER/LEFT | OTHER DAMAGES | INWERKING LAK |            |
|-----|--------------------|---------------|---------------|------------|
|     | Repair paint - LI  | New paint - E | Depr.         | Total      |
| 1   | 0 LU =0.00 EUR     | 290.08 EUR    | 50 %          | 290.08 EUR |

| 1      | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|---|---|---|---|---|---|---|---|----|
| 290.08 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| 145.04 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                     |
|------------|-------------|---------|---------------------|
| 0          | 290.08      | 0       | <b>290.08</b>       |
| HOG: 0     | BG: 0       |         | NA Deprec. 145.04   |
|            |             |         | 0.00%               |
|            |             |         | <b>TOTAL 145.04</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|   |  |   |
|---|--|---|
| <b>Extra Time :</b> 0 min                   | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No<br><b>Reason :</b> |  |   |
| <b>Remark :</b>                             |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 07/11/2017 <b>Hour :</b> 15:37<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| <b>Signature authorized by customer</b><br><br>  |                                |