

D7WWYI

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	128019 KM
File nr. :	1455101	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FBT895 / WAUZZZ8RXDA095684 /		yr of constructionr :	/
E-File nr. :		First registration :	17/05/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / Q5	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	PURATOS NV	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	Q5 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	Yes
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]	VREDESTEIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	65	R	17	W
Rear tyre	235	65	R	17	V

Remark : COMPRESSOR OK

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

[x] FRONT/LEFT OTHER DAMAGES LAK KOMT LOS = OVBH

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE + DEEL TE POL.

[x] FRONT DOOR/RIGHT/FRONT DENT

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

Interior

[x] CARPET FL BURNT

[x] BOOT LID IN SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/REAR DENT +POL.

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] THRESHOLD FRONT/LEFT/CENTER SCRATCH WITH PAINT DAMAGE (DEUR ONDERAAN)

Number	Code	Description	Unit price	Depr.	Total
2	10 LU	Repair paint - LI	48.00 EUR	50 %	48.00 EUR
		New paint - E	0 EUR		

[x] FRONT MUDGUARD/LEFT/CENTER DENT + KRAS

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	DOORSTEP	300.00 EUR	50 %	300.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	348.00	63.00	0	0	0	0	0	0	0
63.00	174.00	63.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
126.00	348.00	0	474.00
HOG: 0	BG: 2		NA Deprec. 300.00
			0.00%
			TOTAL 300.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 03/11/2017 Hour : 11:39 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	