

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	124710 KM
File nr. :	1442371	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DWT772 / WWZZZ7NZDV009388 /		yr of constructionr :	/
E-File nr. :		First registration :	20/09/2012
VFS-nr. :		Color :	BLUE D
Make + Model :	VOLKSWAGEN / SHARAN	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC GROEP NV	Co2:	143g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	SHARAN Trendline BMT 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1968
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	RUIT RV MECHANISME STUK		

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	[x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT DOOR/LEFT/REAR DENT
- [x] FRONT BUMPER/LEFT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	DENT							
			Repair paint - LI	New paint - E		Depr.		Total	
3	0 LU =0.00 EUR		254.16 EUR			50 %		254.16 EUR	
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE							
			Repair paint - LI	New paint - E		Depr.		Total	
2	0 LU =0.00 EUR		369.84 EUR			50 %		369.84 EUR	
[x]	REAR DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE							
	Number	Code	Description		Unit price	Depr.		Total	
1	I 1	i-vab-sp-01	SPOTREPAIR		115.56 EUR			115.56 EUR	
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE							
			Repair paint - LI	New paint - E		Depr.		Total	
2	0 LU =0.00 EUR		382.02 EUR			50 %		382.02 EUR	
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE							
			Repair paint - LI	New paint - E		Depr.		Total	
2	0 LU =0.00 EUR		382.02 EUR			50 %		382.02 EUR	

1	2	3	4	5	6	7	8	9	10
115.56	1133.88	254.16	0	0	0	0	0	0	0
115.56	566.94	127.08	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	1388.04	0	1503.60
HOG: 0	BG: 2		NA Deprec. 809.58
			0.00%
			TOTAL 809.58

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 27/09/2017 Hour : 11:51 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	