

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	102901 KM
File nr. :	1454830	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FQQ720 / YV1DZ88A1E2535712 /		yr of constructionr :	/
E-File nr. :		First registration :	25/09/2013
VFS-nr. :		Color :	BROWN
Make + Model :	VOLVO / XC60	Fuel type :	DIESEL
Object nr. :	11552	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	INVE TECHNOLOGIES NV	Co2:	139g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	XC60 D4 Kinetic 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1984
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :			/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :			/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	235	60	R	18	V
Rear tyre	235	60	R	18	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

	Repair paint - LI	New paint - E	Depr.	Total
[x] REAR BUMPER/CENTER/RIGHT				
2 5 LU =24.00 EUR	211.80 EUR		50 %	235.80 EUR
[x] REAR MUDGUARD/RIGHT/CENTER				
1 5 LU =24.00 EUR	308.20 EUR		50 %	332.20 EUR
[x] FRONT THRESHOLD/RIGHT/REAR				
3 10 LU =48.00 EUR	310.50 EUR		50 %	358.50 EUR

Accessories and others

	Repair paint - LI	New paint - E	Depr.	Total
[x] SUN ROOF				
4 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	SPOILER	100.00 EUR	50 %	100.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	DOORSTEP	250.00 EUR	50 %	250.00 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	SCHUIFDAK	503.00 EUR	50 %	503.00 EUR

1	2	3	4	5	6	7	8	9	10
332.20	335.80	608.50	623.00	0	0	0	0	0	0
166.10	167.90	304.25	311.50	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1899.50	0	1899.50
HOG: 0	BG: 0		NA Deprec. 949.75
			0.00%
			TOTAL 949.75

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 14:50 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	