

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	94178 KM
File nr. :	1454323	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GJL181 / WVWZZZ7NZEV024800 /		yr of constructionr :	/
E-File nr. :		First registration :	24/02/2014
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / SHARAN	Fuel type :	DIESEL
Object nr. :	48092	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BOSE BVBA	Co2:	143g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0		0	
Rear tyre	0	0		0	

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/FRONT	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		382.02 EUR		50 %	382.02 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
3	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	58.32 EUR

HUB CAP REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

1	2	3	4	5	6	7	8	9	10
36.00	382.02	58.32	0	0	0	0	0	0	0
18.00	191.01	58.32	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.32	418.02	0	476.34
HOG: 0	BG: 2		NA Deprec. 267.33
			0.00%
			TOTAL 267.33

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	