

D77V0R

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|------------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: DIRTY [x] EXT: DIRTY [x] |
| Owner : | | Mileage : | 121391 KM |
| File nr. : | 1454556 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1DGE993 / YV1MW84F1C2695722 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 09/05/2012 |
| VFS-nr. : | | Color : | BLACK |
| Make + Model : | VOLVO / V50 | Fuel type : | DIESEL |
| Object nr. : | 34228 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | DE PERSGROEP PUBLISHING NV | Co2: | 99g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | V50 BRE DRIVe Start/Stop 99g 115PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|--------------------------------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1560 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 114 | kW: | 84 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | Yes, winter tires without rims |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | OK [x] |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|----------------------------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | 4-6/ | Rim : | [x] | WHEEL SCRATCHED / Hubcap : |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK | [x] | 4-6/ | Rim : | / Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | 4-6/ | Rim : | [x] | WHEEL SCRATCHED / Hubcap : |
| Wheel RES: | [x] | | Tyre : | OK | / | | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 55 | R | 16 | V |
| Rear tyre | 205 | 55 | R | 16 | V |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | | |
|-----|-------------------------|---------------|---------------------------|----------------------|--------------|--------------|
| [x] | REAR BUMPER/RIGHT/RIGHT | | SCRATCH WITH PAINT DAMAGE | +DEUK | | |
| | | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | 0 LU =0.00 EUR | | 211.80 EUR | | 50 % | 211.80 EUR |
| [x] | ROOF/CENTER/RIGHT | | DENT | | 3X | |
| | Number | Code | Description | Unit price | Depr. | Total |
| 4 | I 1 | i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |
| | Number | Code | Description | Unit price | Depr. | Total |
| 4 | I 1 | i-vab-uitd-02 | BEAT OUT DENT SUPPL | 19.80 EUR | | 19.80 EUR |
| | Number | Code | Description | Unit price | Depr. | Total |
| 4 | I 1 | i-vab-uitd-02 | BEAT OUT DENT SUPPL | 19.80 EUR | | 19.80 EUR |
| [x] | FRONT BUMPER/LEFT | | HOLE/CRACK/TORN | | | |
| | | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | | 0 EUR | | 50 % | |
| | | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 20 LU =96.00 EUR | | 0 EUR | 235.80 EUR | 50 % | 331.80 EUR |

Others

CLEANLINESS INTERIOR

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|--------------------------------------|-------------------|-----------|-----------|
| 1 | I 1 | specifiek-per-kwartier-a-vab-rein-03 | CLEANING INTERIOR | 14.58 EUR | 14.58 EUR |

RIM REAR LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 1 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM REAR RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 1 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|--------------|------------|-------|------------|
| 2 | 1 | FRONT BUMPER | 403.20 EUR | 50 % | 403.20 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|---|---|---|---|---|----|
| 204.58 | 735.00 | 211.80 | 102.60 | 0 | 0 | 0 | 0 | 0 | 0 |
| 204.58 | 367.50 | 105.90 | 102.60 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 307.18 | 946.80 | 0 | 1253.98 |
| HOG: 0 | BG: 0 | | NA Deprec. 780.58 |
| | | | 0.00% |
| | | | TOTAL 780.58 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |