

www.vabfleetservices.be

### **APPRAISAL**

06/11/2017 Date :

#### [] NOT EXECUTED **[X] EFFECTIVE**

[] COLLECTION

[] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	223732 KM
File nr. :	1456608	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EYF307 / WBAXB91040DX	746792 /	yr of constructionr :	/
E-File nr. :		First registration :	19/04/2013
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 5	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	L	Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	143g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
нр:	211	kW:	155
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	

1/5

D9VZHZ

# fleet services

### **APPRAISAL**

www.vabfleetservices.be

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	ОК	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[X]	Filled up :	0	

#### Wheels and tyres: Summer tires

	t tyre r tyre	_	225 225	_	55 55			R R		17 17	W	
		[x]	Width			He	eight			Туре	Rim	Index
Wheel RES:	[x]		Tyre :		OK		/	Rim :			/ Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :		ОК	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :		OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :	
Wheel FL:	[x]	MICHELIN	Tyre :		OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :	

#### Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/ Hubcap :

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

2/5



### **APPRAISAL**

www.vabfleetservices.be

Date :

06/11/2017

3/5

#### STATUS: ACCEPTABLE / USAGE DAMAGE

Во	dywork \& windows					
[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAI	NT DAMAGE		
[x]	REAR BUMPER/CENTER/RIGHT		SCRATCH WITH PAI	NT DAMAGE		
[x]	REAR WINDOW/LEFT		SCRATCH WITH PAI	NT DAMAGE		
[x]	REAR WINDOW STYLE/CENTER/LEF	T/UP	SCRATCH WITH PAI	NT DAMAGE		
[x]	REAR MUDGUARD/RIGHT/CENTER		SCRATCH (WITHOU	T PAINT DAMAGE	5)	
[x]	REAR DOOR/RIGHT/CENTER		SCRATCH (WITHOU	T PAINT DAMAGE		
[x]	WINDSCREEN/CENTER/LEFT		WINDOW DAMAGE		HERSTELD	
[x]	FRONT DOOR/RIGHT/CENTER		SCRATCH (WITHOU	T PAINT DAMAGE	5)	
[x]	FRONT MUDGUARD/RIGHT/CENTER		SCRATCH (WITHOU	T PAINT DAMAGE	5)	
[x]	FRONT BUMPER/CENTER/RIGHT		SCRATCH WITH PAI	NT DAMAGE		
[x]	FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAI	NT DAMAGE		
Inte	erior					
[x]	SEAT FL		SCRATCHED			
Ac	cessories and others					
[x]	OUTSIDE MIRROR		SCRATCH (WITHOU	T PAINT DAMAGE		
ST	ATUS: NOT ACCEPTA	BLE				
Во	dywork \& windows					
[x]	FRONT DOOR/LEFT/CENTER		DENT			
	Number Code	Description		Unit price	Depr.	Total
	1 I 1 i-vab-uitd-01	BEAT OUT DENT		63.00 EUR		63.00 EUR
Inte	erior					
[x]	SEAT REAR RIGHT		OTHER DAMAGES			
		Repair paint - LI	New paint - E		Depr.	Total
	<b>2</b> 10 LU =48.00 EUR	0 EUR			50 %	48.00 EUR



### APPRAISAL

eces									
Number	Code		Description			Unit pri	ice Depr.		Total
2 1	OPBERGVAK					52.00 EU	UR 50 %		52.00 EUR
1	2	3	4	5	6	7	8	9	10
63.00	100.00	0	0	0	0	0	0	0	0
63.00	50.00	0	0	0	0	0	0	0	0
INNOV	ATIVE	TRADI	TIONAL	GI	ENERAL				
63	.00	100.00			0				163
HO	G: 0	В	BG: 2			NA Dep	rec.		1
						0.00%	6		
						ТОТА	L		113

# VAB fleet services

## APPRAISAL

www.vabfleetservices.be

Date : 06/11/2017

[x] = Status Modification

#### Pictures : No CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason :		Reason :	
NOT EXECUTED :	No				
Reason :					
Remark :					

Prices in EUR without VAT

Authorized by customer :				Executed by VAB Fleet Services
Remark authorized cust	tomer :			
Date :	06/11/2017	Hour :	12:56	
Company :				
Executed by VAB Fleet Services				
E-Mail :	@			
Signature authorized by c	ustomer			

5/5