

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	183188 KM
File nr. :	1455221	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GVQ899 / VF7SC9HPKEW586602 /		yr of constructionr :	/
E-File nr. :		First registration :	13/05/2014
VFS-nr. :		Color :	BLACK
Make + Model :	CITROEN / C3	Fuel type :	DIESEL
Object nr. :	52579	Fuel :	
Classification :	A	Environment Class:	EURO 5
Customer company :	DOLCE LA HULPE SA	Co2:	90g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	92	kW:	68
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	Yes
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :			

	Width	Height	Type	Rim	Index
Front tyre	0	0		0	
Rear tyre	0	0		0	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE
[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/CENTER	DENT
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	-------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	THRESHOLD FRONT/LEFT/CENTER	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
2	10 LU =48.00 EUR		248.40 EUR		50 %
					296.40 EUR
[x]	FRONT DOOR/LEFT/CENTER	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
2	10 LU =48.00 EUR		254.68 EUR		50 %
					302.68 EUR
[x]	FRONT MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
2	0 LU =0.00 EUR		176.14 EUR		50 %
					176.14 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT	DENT			
	Number	Code	Description	Unit price	Depr.
					Total
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	
					63.00 EUR
[x]	ROOF/CENTER/LEFT	DENT			
	Number	Code	Description	Unit price	Depr.
					Total
3	I 3	i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR	
					293.40 EUR

Interior

[x]	CARPET FL		BURNT			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR		43.92 EUR
[x]	ROOF UPHOLSTERY		BURNT			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR		64.32 EUR

Accessories and others

[x]	LUGGAGE RACK		MISSING/INCOMPLETE			
			Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR		0 EUR		50 %	

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-geur-01	ODOUR TREATMENT	152.58 EUR		152.58 EUR
	HUB CAP FL					
			Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR				50 %	
	HUB CAP REAR L					
			Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR				50 %	
	HUB CAP FR					
			Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR				50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	SLEUTEL BAGAGEDRAGER	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
260.82	775.22	293.40	63.00	72.00	30.00	0	0	0	0
260.82	387.61	293.40	63.00	36.00	15.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
617.22	877.22	0	1494.44
HOG: 0	BG: 1		NA Deprec. 1055.83
			0.00%
			TOTAL 1055.83

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 13:48 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	