

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	55483 KM
File nr. :	1447562	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
HL8314 / WBAXX110500R37308 /		yr of constructionr :	/
E-File nr. :		First registration :	16/10/2015
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / X4	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	PWC	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	190	kW:	140
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	17	V
Rear tyre	225	60	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE		
[x]	REAR DOOR/CENTER/RIGHT	DENT	MET LAKSCHADE	
[x]	FRONT DOOR/RIGHT/CENTER	DENT		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/CENTER	DENT				
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			+KRAS KOETSWERK/AANV.	
		Repair paint - LI	New paint - E		Depr.	Total
2	5 LU	=24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	60.00	0	0	0	0	0	0	0	0
63.00	30.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	60.00	0	123.00
HOG: 0	BG: 2		NA Deprec. 93.00
			0.00%
			TOTAL 93.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE VERY DIRTY

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/10/2017 Hour : 10:20 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	