

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: VERY DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	24733 KM
File nr. :	1451016	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1PYU419 / ZCFC635A405116215 /		yr of constructionr :	/
E-File nr. :		First registration :	13/10/2016
VFS-nr. :		Color :	WHITE
Make + Model :	IVECO / DAILY	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	227g/km
Driver :		Remote controls:	1
Covering :	IMITATION LEATHER	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	2998
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	146	kW:	107
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :		Service manual :	NOK	<input type="checkbox"/>
Cert. of reg. / Part 1:	NOK <input type="checkbox"/> MISSING/INCOMPLETE	Cert. of conformity :	NOK	<input type="checkbox"/> MISSING/INCOMPLETE
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK <input type="checkbox"/>	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	<input type="checkbox"/>
Mobile phone kit :		Extinguisher :	OK	<input type="checkbox"/>
First aid kit :	OK <input type="checkbox"/>	Warning triangle :	OK	<input type="checkbox"/>
Jack, wheelspanner :	OK <input type="checkbox"/>	Oil level :	OK	<input type="checkbox"/>
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	<input type="checkbox"/>	CONTINENTAL	Tyre :	OK	<input type="checkbox"/>	2-4/	Rim :	/	Hubcap :	
Wheel RL :	<input type="checkbox"/>	CONTINENTAL	Tyre :	OK	<input type="checkbox"/>	2-4/	Rim :	/	Hubcap :	
Wheel FR :	<input type="checkbox"/>	CONTINENTAL	Tyre :	<input type="checkbox"/>	OK	<input type="checkbox"/>	2-4/	Rim :	/	Hubcap :
Wheel RR :	<input type="checkbox"/>	CONTINENTAL	Tyre :	OK	<input type="checkbox"/>	2-4/	Rim :	/	Hubcap :	
Wheel RES:	<input type="checkbox"/>		Tyre :	OK		/	Rim :	/	Hubcap :	

<input type="checkbox"/>	Width	Height	Type	Rim	Index
Front tyre	195	75	R	16	R
Rear tyre	195	75	R	16	R

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

<input type="checkbox"/>	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

Accessories and others

[x] VEH COVERED WITH STICKERS STICKER(S)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/RIGHT/RIGHT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
3 15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR

[x] REAR MUDGUARD/CENTER/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	193.71 EUR		50 %	193.71 EUR

[x] REAR MUDGUARD/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR

[x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR

Interior

[x] SEAT FL MISSING/INCOMPLETE

	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
5 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 10	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		145.80 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	HENDEL	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	SIDE PROTECTION	10.80 EUR	50 %	10.80 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	SIDE PROTECTION	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	MIRROR	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
199.80	193.71	329.40	510.71	114.00	0	0	0	0	0
172.80	96.86	164.70	255.36	57.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
145.80	1201.82	0	1347.62
HOG: 0	BG: 3		NA Deprec. 746.71
			0.00%
			TOTAL 746.71

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : DOCUMENTEN ZIJN COPIES [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 09/11/2017 Hour : 13:16 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	