

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: VERY DIRTY [x] EXT: VERY DIRTY [x]
Owner :		Mileage :	149124 KM
File nr. :	1456898	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
403BTL / ZFA25000001788325 /		yr of constructionr :	/
E-File nr. :		First registration :	14/06/2010
VFS-nr. :		Color :	SILVER
Make + Model :	FIAT / DUCATO	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	IMTECH PROJECTS ALKEN	Co2:	g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	DUCATO 35 B/F MWB 100pk	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	2198
Gear box :	Manueel	Number of places:	3
Number of gears:		Number of doors:	5
HP:	101	kW:	74
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	NOK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	215	70	R	15	M+S
Rear tyre	215	70	R	15	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	ROOF STYLE/CENTER/LEFT	OTHER DAMAGES	ROESTVLEKKEN
[x]	ROOF STYLE/CENTER/RECHTS	OTHER DAMAGES	ROESTVLEKKEN
[x]	BONNET/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
-----	---------------------------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/CENTER/LEFT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
	4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
	5	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR
[x]	WINDSCREEN/LEFT	WINDOW DAMAGE				
	Number	Code	Description	Unit price	Depr.	Total
	3	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
	6	0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUR
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE				
	Number	Code	Description	Unit price	Depr.	Total
	2	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

Interior

[x]	DASHBORD	MISSING/INCOMPLETE				
			Repair paint - LI	New paint - E	Depr.	Total
	1	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

Accessories and others

[x] OUTSIDE MIRROR LEFTHAND SIDE

BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
8 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 10	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	145.80 EUR

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	2	DRAAIKNOP	20.00 EUR	50 %	40.00 EUR

Number	Code	Description	Unit price	Depr.	Total
7	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

Number	Code	Description	Unit price	Depr.	Total
8	1	MIRROR	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
233.80	110.64	58.80	63.00	231.15	165.13	22.50	114.00	0	0
189.80	110.64	58.80	63.00	115.58	82.56	11.25	57.00	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
378.24	620.78	0	999.02
HOG: 0	BG: 3		NA Deprec. 688.63
			0.00%
			TOTAL 688.63

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE VERY DIRTY

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/11/2017 Hour : 09:30 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	