

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	125747 KM
File nr. :	1451972	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EBQ343 / WDD2462001J113614 /		yr of constructionr :	2012 / 10
E-File nr. :		First registration :	12/10/2012
VFS-nr. :		Color :	BROWN
Make + Model :	MERCEDES / B	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ILOMAR NV	Co2:	113g/km
Driver :		Remote controls:	2
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	B 180 CDI BE 109PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1796
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] UNIROYAL Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RL : [x] DUNLOP Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel FR : [x] UNIROYAL Tyre : [x] OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RR : [x] DUNLOP Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/LEFT/CORNER/BELOW	SCRATCH WITH PAINT DAMAGE	INT
[x]	ROOF/CENTER/RIGHT	DENT	+ HARSRESTEN
[x]	REAR DOOR/RIGHT/CORNER/BELOW	DENT	INT

Interior

[x]	SEAT FL	CUT / TORN
-----	---------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

	HUB CAP FL				
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	
	HUB CAP REAR RIGHT				
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	
	HUB CAP FR				
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
90.00	211.80	211.80	0	0	0	0	0	0	0
45.00	105.90	105.90	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	513.60	0	513.60
HOG: 0	BG: 0		NA Deprec. 256.80
			0.00%
			TOTAL 256.80

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 03/11/2017 Hour : 11:39 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	