

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	103966 KM
File nr. :	1450952	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FER177 / WF0KXXGCBKDB70347 /		yr of constructionr :	/
E-File nr. :		First registration :	10/06/2013
VFS-nr. :		Color :	BLUE D
Make + Model :	FORD / FOCUS	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	WIRELESS TECHNOLOGIES BVBA	Co2:	88g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	FOCUS BER EConetic Trend 88g 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	NOK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	OK
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel RL :	MICHELIN	Tyre :	OK		4-6/	Rim :	/	Hubcap :			
Wheel FR :	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	MICHELIN	Tyre :	OK		4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	MICHELIN	Tyre :	OK		>6/	Rim :	/	Hubcap :			

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	ROOF STYLE/CENTER/RIGHT	DENT
[x]	REAR DOOR/RIGHT/CENTER	DENT
[x]	FRONT DOOR/RIGHT/REAR	DENT
[x]	FRONT DOOR/RIGHT/CENTER	DENT
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE	+SPOILER		
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	211.80 EUR		50 %	235.80 EUR

Others

	HUB CAP FL				
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SPOILER	75.00 EUR	50 %	75.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
310.80	30.00	0	0	0	0	0	0	0	0
155.40	15.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	340.80	0	340.80
HOG: 0	BG: 0		NA Deprec. 170.40
			0.00%
			TOTAL 170.40

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 02/11/2017 Hour : 09:09 Company : Executed by VAB Fleet Services E-Mail :	Executed by VAB Fleet Services
Signature authorized by customer 	