

CY6ZA1

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	188937 KM
<b>File nr. :</b>	1447423	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1HDP229 / SJNFAAJ11U1047718 /		<b>yr of constructionr :</b>	2014 / 06
<b>E-File nr. :</b>		<b>First registration :</b>	25/06/2014
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	NISSAN / QASHQAI	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	37802	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	KBC GROEP NV	<b>Co2:</b>	99g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	SUV	<b>Engine size:</b>	1461
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	110	<b>kW:</b>	81
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	17	H
Rear tyre	215	60	R	17	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## Conclusion

### Interior

[x] SEAT FL CUT / TORN

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT		SCRATCH WITH PAINT DAMAGE	MEERDERE	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR
[x]	REAR MUDGUARD/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE	MEERDERE	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR	258.28 EUR		50 %	258.28 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT		DENT		
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
6	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR THRESHOLD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE	BINNEN	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
4	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	REAR THRESHOLD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE	BINNEN	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
4	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	THRESHOLD FRONT/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE	BINNEN	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
4	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	FRONT THRESHOLD/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE	BINNEN	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
4	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

[x]	FRONT BUMPER/CENTER/RIGHT		DENT		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	0 EUR		50 %	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR
[x]	FRONT WHEEL/RIGHT		SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
7	0 LU =0.00 EUR	0 EUR		50 %	

## Interior

[x]	DOOR IN REAR L		SCRATCHED			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
1	I 1	i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR
[x]	DOOR IN REAR RIGHT		SCRATCHED			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
1	I 1	i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR
[x]	BOOT LID IN		SCRATCHED			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
1	I 1	i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

## Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE		BROKEN / CRACKED		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

## Others

CLEANLINESS INTERIOR

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		58.32 EUR

<b>Pieces</b>
---------------

Number	Code	Description	Unit price	Depr.	Total
2	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR
3	1	MIRROR	120.00 EUR	50 %	120.00 EUR
5	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR
7	1	SIDE PROTECTION	14.40 EUR	50 %	14.40 EUR

1	2	3	4	5	6	7	8	9	10
390.24	499.20	168.00	462.24	697.48	63.00	14.40	0	0	0
390.24	249.60	84.00	462.24	348.74	63.00	7.20	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
915.48	1379.08	0	<b>2294.56</b>
HOG: 0	BG: 0		NA Deprec. 1605.02
			0.00%
			<b>TOTAL 1605.02</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 31/10/2017 <b>Hour :</b> 10:45 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	