

www.vabfleetservices.be Date: 06/11/2017 1/5

D113TE

### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	88663 KM
File nr. :	1449616	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FTK006 / KMHLB81UADU	063905 /	yr of constructionr :	/
E-File nr. :		First registration :	17/09/2013
VFS-nr. :		Color :	SILVER
Make + Model :	HYUNDAI / I40	Fuel type :	DIESEL
Object nr. :	69404	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company:	ALTEREGO DESIGN	Co2:	113g/km
Driver :		Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	i40 BRE Blue Drive 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes			
Variant car:	BREAK	Engine size:	1685			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	5			
HP:	116	kW:	85			
Fisc HP		Imported vehicle:	No			
Animals transported:	No	Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:						



www.vabfleetservices.be Date: 06/11/2017 2/5

Original registr. number : OK Service manual: OK Cert. of reg. / Part 1: OK Cert. of conformity: OK Insurance certificate : Cert. of reg. copy / Part 2: [x] OK Warning vest: OK Transport licence: Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK Mobile phone kit: Extinguisher: OK Warning triangle: OK

Oil level:

Filled up:

OK

0

Wheels and tyres: Summer tires

OK

Wheel FL: HANGKOOK Tyre: OK 2-4 / Rim: Hubcap: Wheel RL: HANGKOOK Tyre: OK 4-6/ Rim: WHEEL SCRATCHED / Hubcap: Wheel FR: HANGKOOK Tyre: OK 2-4/ Rim: WHEEL SCRATCHED / Hubcap: Wheel RR: HANGKOOK Tyre: OK 4-6/ Rim: / Hubcap: Wheel RES: KUM-HO Tyre: OK 2-4/ Rim: / Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark:

First aid kit:

Jack, wheelspanner:

#### Wheels and tyres:

Wheel FL: Tyre: OK Rim: / Hubcap: Wheel RL: OK Tyre: Rim: / Hubcap: Wheel FR: OK Tyre: Rim: / Hubcap: Wheel RR: Tyre: OK Rim: / Hubcap: Wheel RES: OK Tyre: Rim: / Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



Number Code

i-vab-sp-01

1 I 1

## **APPRAISAL**

Date: 06/11/2017 www.vabfleetservices.be 3/5

ST	ATUS: ACCEPTABLE / I	USAGE DAMA	GE		
Во	dywork \& windows				
[x]	REAR BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE	SPOILER	
[x]	REAR BUMPER/SIDE/LEFTCENTER		SCRATCH WITH PAINT DAMAGE	POLIR	
[x]	REAR MUDGUARD/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE	POLIR+BAS ELEM	MENT .
x]	REAR MUDGUARD/RIGHT/FRONT		OTHER DAMAGES	JUPE/ALIGNEMEN	NT
x]	REAR THRESHOLD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE	IN	
[x]	THRESHOLD FRONT/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		
[x]	FRONT THRESHOLD/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE		
[x]	BONNET/CENTER/LEFT		OTHER DAMAGES	ISOLATION	
[x]	FRONT MUDGUARD/RIGHT/REAR		SCRATCH (WITHOUT PAINT DAMAGE)	POLIR	
[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE		
Inte	erior				
[x]	SEAT FL		SCRATCHED		
Ac	cessories and others				
	OUTSIDE MIRROR		SCRATCH WITH PAINT DAMAGE		
ST	ATUS: NOT ACCEPTAB	LE			
Во	dywork \& windows				
[x]	REAR MUDGUARD/LEFT/REAR		DENT	POLIR	
		Repair paint - LI	New paint - E	Depr.	Total
	3 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	REAR DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
	2 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT BUMPER/LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		

Unit price

115.56 EUR

Depr.

Total

115.56 EUR

Description

SPOTREPAIR



www.vabfleetservices.be Date: 06/11/2017 4/5

#### Others

RIM REAR LEFT

I	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
115.56	318.35	308.20	95.00	0	0	0	0	0	0
115.56	159.18	154.10	95.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
210.56	626.55	0		837.11
HOG: 0	BG: 0		NA Deprec.	523.84
			0.00%	
			TOTAL	523.84



www.vabfleetservices.be Date: 06/11/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMSTANCES			NORMAL CONCLUSION			
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min	
NOT EXECUTED Reason:	: No					
Remark:						
Prices in EUR	without VAT					
Authorized by customer:			Executed by VAB Fleet S	Services		
Remark authorized	d customer :					
Date :	06/11/2017	<b>Hour:</b> 15:56				
Company:  Executed by VAB I Services	Fleet					
E-Mail :	@					
Signature authorized	d by customer					