

D2MOXL

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	13532 KM
File nr. :	1450899	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1PYU097 / ZCFC635A005113649 /		yr of constructionr :	/
E-File nr. :		First registration :	01/01/1918
VFS-nr. :		Color :	WHITE
Make + Model :	IVECO / DAILY	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	1
Covering :	IMITATION LEATHER	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	5 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	NOK	[x]
Cert. of reg. / Part 1:	NOK	[x]	Cert. of conformity :	NOK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	>6/	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	75	R	16	
Rear tyre	195	75	R	16	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Interior

[x] SEAT FL		OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	0 EUR		50 %	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 10	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	114.70 EUR
Number	Code	Description	Unit price	Depr.	Total
1	I 5	bestelwagen-laadruimte-a-vab-rein-06	CLEANING INTERIOR	23.41 EUR	117.05 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	AFDEKPLAAT	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
231.75	30.00	0	0	0	0	0	0	0	0
231.75	15.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
231.75	30.00	0	261.75
HOG: 0	BG: 3		NA Deprec. 246.75
			0.00%
			TOTAL 246.75

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 09/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	