

www.vabfleetservices.be Date: 07/11/2017 1/4

D8OURI

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	120149 KM
File nr. :	1455684	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FVI588 / WMWZD31000WF	93434 /	yr of constructionr :	/
E-File nr. :		First registration :	06/11/2013
VFS-nr. :		Color :	BLACK
Make + Model :	MINI / COUNTRYMAN	Fuel type :	DIESEL
Object nr. :	47080	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	Ordina Belgium NV	Co2:	115g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	MINI COUNTRYMAN Cooper D DPF 112PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	112	kW:	82
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:		ı	



www.vabfleetservices.be Date: 07/11/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Varning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Tuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
ack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MI	CHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap :	
Wheel RL	: [x]	MI	CHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR	: [x]	MI	CHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RR	: [x]	MI	CHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RE	S: [x]			Tyre:		OK		/	Rim:		/	Hubcap:	
		[x]		Width	Ì		Н	eight		Туре		Rim	Index
F	ront tyr	e		205				60		R		16	Н
F	Rear tyre)		205				60		R		16	Н

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	[x]	Width	Height	Type	Rim	Index
Front	t tyre	0	0	R	0	
Rear	tyre	0	0	R	0	

Remark:

Remark:



www.vabfleetservices.be Date: 07/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Во	Bodywork \& windows							
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE						

[x] REAR DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Во	dywork \& windows				
[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAG	GE	
		Repair paint - LI	New paint - E	Depr.	Total
	3 0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR
[x]	BONNET/RIGHT/CENTER		OTHER DAMAGES	INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
	2 0 LU =0.00 EUR	232.06 EUR		50 %	232.06 EUR

Interior

[x] FLOOR BOOT STAIN

Number	r Code	Description	Unit price	Depr.	Total
1 I1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

1	2	3	4	5	6	7	8	9	10
14.58	232.06	169.44	0	0	0	0	0	0	0
14.58	116.03	84.72	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
416.08	0	401.50	14.58
NA Deprec. 215.33		BG: 1	HOG: 0
0.00%			

0.00% TOTAL 215.33



www.vabfleetservices.be Date: 07/11/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMST	ANCES		NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 min Reason:	n	Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No							
Remark :								
Prices in EUR wit	thout VAT							
Authorized by customer :			Executed by VAB Fleet So	ervices				
Remark authorized cu	istomer :							
Date :	07/11/2017	Hour: 11:44						
Company: Executed by VAB Flee Services	et							
E-Mail :	@							
Signature authorized by	customer	_						