

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	180493 KM
<b>File nr. :</b>	1453817	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1CMG632 / VF30U9HR8BS346791 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	03/01/2012
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	PEUGEOT / 3008	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	56680	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	WUST SA	<b>Co2:</b>	130g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	3008 Premium FAP 112PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	SUV	<b>Engine size:</b>	1560
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	112	<b>kW:</b>	82
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	[x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	Tyre :	OK /	Rim :	[x] WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	Tyre :	OK /	Rim :		/	Hubcap :
Wheel FR :	Tyre :	OK /	Rim :	[x] WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	Tyre :	OK /	Rim :	[x] WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	Tyre :	OK /	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	V
Rear tyre	225	50	R	17	V

Remark :

## Wheels and tyres:

Wheel FL:	Tyre :	OK /	Rim :		/	Hubcap :
Wheel RL :	Tyre :	OK /	Rim :		/	Hubcap :
Wheel FR :	Tyre :	OK /	Rim :		/	Hubcap :
Wheel RR :	Tyre :	OK /	Rim :		/	Hubcap :
Wheel RES:	Tyre :	OK /	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] FRONT BUMPER/RIGHT/CORNER SCRATCH (WITHOUT PAINT DAMAGE)

### Accessories and others

[x] OUTSIDE MIRROR LEFTHAND SIDE SCRATCH (WITHOUT PAINT DAMAGE)

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR DOOR/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR

[x] REAR MUDGUARD/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE +DEUKEN

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

### Interior

[x] BOOT LID IN SCRATCHED

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 3 speciefiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		43.74 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
43.74	190.00	301.68	308.20	110.64	0	0	0	0	0
43.74	190.00	150.84	154.10	110.64	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
344.38	609.88	0	<b>954.26</b>
HOG: 0	BG: 0		NA Deprec. 649.32
			0.00%
			<b>TOTAL 649.32</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 06/11/2017 <b>Hour :</b> <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b> 	