

D7NJ10

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	171841 KM
File nr. :	1454909	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1JUR451 / WOLGT8ES0F1027909 /		yr of constructionr :	/
E-File nr. :		First registration :	02/03/2015
VFS-nr. :		Color :	BLACK
Make + Model :	OPEL / INSIGNIA BREAK	Fuel type :	DIESEL
Object nr. :	72417	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CEGELEC BUILDING SERVICES	Co2:	104g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1956
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	140	kW:	103
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	DUNLOP	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	Y
Rear tyre	225	55	R	17	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	BONNET/LEFT/CENTER	OTHER DAMAGES	CHEM. INWERKING	
	Repair paint - LI	New paint - E	Depr.	
			Total	
1	0 LU =0.00 EUR	290.08 EUR	50 %	290.08 EUR

1	2	3	4	5	6	7	8	9	10
290.08	0	0	0	0	0	0	0	0	0
145.04	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	290.08	0	290.08
HOG: 0	BG: 0		NA Deprec. 145.04
			0.00%
			TOTAL 145.04

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	