

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	185495 KM
File nr. :	1457924	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
QW4903 / VF37J9HP0DN509507 /		yr of constructionr :	/
E-File nr. :		First registration :	10/04/2013
VFS-nr. :		Color :	RED
Make + Model :	PEUGEOT / PARTNER TEPEE	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	92	kW:	68
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :		
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]		
Tax certificate :		Transport licence :		
Fuel card :		Navigation CD/SD/DVD		
Mobile phone kit :		Car radio :	OK	[x]
First aid kit :	OK	[x]		
Jack, wheelspanner :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	205	65	R	15	H
Rear tyre	205	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] WINDSCREEN/RIGHT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/RIGHT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
9	0 LU =0.00 EUR		241.34 EUR		50 %
					241.34 EUR
[x]	REAR MUDGUARD/LEFT/Front	SCRATCH WITH PAINT DAMAGE			+DEUKEN
			Repair paint - LI	New paint - E	Depr.
					Total
8	0 LU =0.00 EUR		246.56 EUR		50 %
					246.56 EUR
[x]	REAR MUDGUARD/RIGHT/Front	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
10	0 LU =0.00 EUR		246.56 EUR		50 %
					246.56 EUR
[x]	REAR DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
8	0 LU =0.00 EUR		254.68 EUR		50 %
					254.68 EUR
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
10	0 LU =0.00 EUR		254.68 EUR		50 %
					254.68 EUR
[x]	FRONT THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			+DEUKEN BINNENIN
			Repair paint - LI	New paint - E	Depr.
					Total
3	0 LU =0.00 EUR		248.40 EUR		50 %
					248.40 EUR
[x]	FRONT DOOR/LEFT/Front	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
6	0 LU =0.00 EUR		254.68 EUR		50 %
					254.68 EUR
[x]	WINDSCREEN/CENTER/LEFT	HOLE/CRACK/TORN			HERSTELD
	Number	Code	Description	Unit price	Depr.
					Total
0	0				

[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR	254.68 EUR		50 %	254.68 EUR

[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	176.14 EUR		50 %	176.14 EUR

[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR

Interior

[x]	BOOT LID IN	OTHER DAMAGES			
	Number Code	Description	Unit price	Depr.	Total
10	I 2 i-vab-ander-01	REPAIR (PER 15')	18.74 EUR		37.48 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR	0 EUR		50 %	

Others

CLEANLINESS INTERIOR

	Number Code	Description	Unit price	Depr.	Total
1	I 5 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		72.90 EUR

HUB CAP FL

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

HUB CAP REAR L

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	SIDE PROTECTION	11.52 EUR	50 %	11.52 EUR
Number	Code	Description	Unit price	Depr.	Total
7	1	MIRROR COVER	96.00 EUR	50 %	96.00 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	SIDE PROTECTION	11.52 EUR	50 %	11.52 EUR

1	2	3	4	5	6	7	8	9	10
72.90	48.00	248.40	169.44	176.14	266.20	96.00	501.24	241.34	804.92
72.90	24.00	124.20	84.72	88.07	133.10	48.00	250.62	120.67	421.20

INNOVATIVE	TRADITIONAL	GENERAL	
110.38	2514.20	0	2624.58
HOG: 0	BG: 1		NA Deprec. 1367.48
			0.00%
			TOTAL 1367.48

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 09/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	