

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	94020 KM
File nr. :	1455898	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
YRY139 / VF3YAAMFB11500906 /		yr of constructionr :	/
E-File nr. :		First registration :	14/08/2008
VFS-nr. :		Color :	
Make + Model :	PEUGEOT / BOXER	Fuel type :	DIESEL
Object nr. :	12509	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	MIVB-STIB OI	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	3 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	BOXER 330 B/F MWB HR L2H2 101PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	2198
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	5
HP:	101	kW:	74
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK [x]	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK [x]	Warning triangle :	OK	[x]
Jack, wheelspanner :	OK [x]	Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	215	70	R	15	H
Rear tyre	215	70	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT DOOR/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE
- [x] FRONT MUDGUARD/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/CENTER/LEFT		DENT						
				Repair paint - LI	New paint - E		Depr.	Total	
5	0 LU =0.00 EUR			193.71 EUR			50 %	193.71 EUR	
[x]	REAR MUDGUARD/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE						
				Repair paint - LI	New paint - E		Depr.	Total	
4	0 LU =0.00 EUR			231.15 EUR			50 %	231.15 EUR	
[x]	REAR MUDGUARD/RIGHT/FRONT		DENT						
				Repair paint - LI	New paint - E		Depr.	Total	
6	15 LU =72.00 EUR			231.15 EUR			50 %	303.15 EUR	
[x]	REAR DOOR/RIGHT/FRONT		DENT						
				Repair paint - LI	New paint - E		Depr.	Total	
7	30 LU =144.00 EUR			0 EUR	326.78 EUR		50 %	470.78 EUR	
[x]	BONNET/CENTER/LEFT/FRONT		DENT						
				Number	Code	Description	Unit price	Depr.	Total
3	1	i-vab-uitd-01		3	I 1	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT BUMPER/RIGHT/SIDE		HOLE/CRACK/TORN						
				Repair paint - LI	New paint - E		Depr.	Total	
2	20 LU =96.00 EUR			0 EUR			50 %	96.00 EUR	

Interior

[x]	FLOOR FR		MISSING/INCOMPLETE					
				Repair paint - LI	New paint - E		Depr.	Total
1	5 LU =24.00 EUR			0 EUR			50 %	24.00 EUR

[x]	SEAT FR		CUT / TORN		
		Repair paint - LI	New paint - E	Depr.	Total
1	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	DOOR IN FL		MISSING/INCOMPLETE		
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	ROOF UPHOLSTERY		CUT / TORN		
		Repair paint - LI	New paint - E	Depr.	Total
1	30 LU =144.00 EUR	0 EUR		50 %	144.00 EUR
[x]	FLOOR BOOT		OTHER DAMAGES		
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces					
Number	Code	Description	Unit price	Depr.	Total
1	1	RAAMBEDIENING	40.00 EUR	50 %	40.00 EUR
		Number Code Description	Unit price	Depr.	Total
1	1	PANEEL	25.00 EUR	50 %	25.00 EUR
		Number Code Description	Unit price	Depr.	Total
1	1	ROOF COAT	262.50 EUR	50 %	262.50 EUR
		Number Code Description	Unit price	Depr.	Total
1	1	SEAT UPHOLSTERY TISSUE	90.00 EUR	50 %	90.00 EUR
		Number Code Description	Unit price	Depr.	Total
2	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
		Number Code Description	Unit price	Depr.	Total
1	1	SLOT	30.00 EUR	50 %	30.00 EUR
		Number Code Description	Unit price	Depr.	Total
7	1	SLINDING DOOR	562.50 EUR	50 %	562.50 EUR

1	2	3	4	5	6	7	8	9	10
783.50	398.40	63.00	231.15	193.71	303.15	1033.28	0	0	0
391.75	199.20	63.00	115.58	96.86	151.58	516.64	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	2943.19	0	3006.19
HOG: 0	BG: 3		NA Deprec. 1534.60
			0.00%
			TOTAL 1534.60

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/11/2017 Hour : 12:49 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	