

www.vabfleetservices.be Date: 09/11/2017 1/5

D8RPTK

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner:		Mileage :	130731 KM
File nr. :	1455748	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ESK203 / W0LPE5EW4DG0	68789 /	yr of constructionr :	/
E-File nr. :		First registration :	08/03/2013
VFS-nr. :		Color :	BROWN L
Make + Model :	OPEL / ASTRA	Fuel type :	DIESEL
Object nr. :	717757	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	LE CARROSSE SA	Co2:	99g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ASTRA SED ecoFLEX Cosmo St/St 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1686
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	Yes
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		l	



09/11/2017 Date: www.vabfleetservices.be 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNI	ROYAL	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap :	
Wheel RL:	[x]	UNI	ROYAL	Tyre:		OK	[x]	>6/	Rim:				/ Hubcap:	
Wheel FR:	[x]	UNI	ROYAL	Tyre:	[x]	OK	[x]	4-6 /	Rim:				/ Hubcap:	
Wheel RR:	[x]	UNI	ROYAL	Tyre:		OK	[x]	>6 /	Rim:				/ Hubcap:	
Wheel RES:	[x]			Tyre:		OK		/	Rim:				/ Hubcap:	
		[x]		Width			Н	eight			Type		Rim	Index
Fron	t tyre			225				50			R		17	Y

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	225	50	R	17	Y
	Rear tyre	225	50	R	17	Y
L					i i	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/	Hubcap :
Wheel RR:	Tyre:	OK	/	Rim:	/	Hubcap :
Wheel RES:	Tyre:	OK	/	Rim:	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 09/11/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

Boo	dywork \& windows					
[x]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAI	NT DAMAGE		
[x]	FRONT DOOR/RIGHT/CENTER		SCRATCH WITH PAI	NT DAMAGE		
[x]	FRONT MUDGUARD/LEFT/REAR		SCRATCH WITH PAI	NT DAMAGE		
[x]	ROOF/CENTER/LEFT		DENT			
ST	ATUS: NOT ACCEPTABL	.E				
Boo	dywork \& windows					
[x]	REAR BUMPER/LEFT/LEFT		SCRATCH WITH PAI	NT DAMAGE		
		Repair paint - LI	New paint - E		Depr.	Total
	2 0 LU =0.00 EUR	211.80 EUR	,		50 %	211.80 EUR
[x]	REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAI	NT DAMAGE		
		Repair paint - LI	New paint - E		Depr.	Total
	3 0 LU =0.00 EUR	318.35 EUR			50 %	318.35 EUR
[x]	BONNET/CENTER/LEFT		DENT			
	Number Code	Description		Unit price	Depr.	Total
	4 I 1 i-vab-uitd-01	BEAT OUT DENT		63.00 EUR		63.00 EUR
Inte	erior					
[x]	SEAT REAR L		HOLE			
	Number Code	Description		Unit price	Depr.	Total
	5 I 1 i-vab-intvlr-01	VELOURS REPAIR (N DIAMATER)	MAX 3CM LENGTH OR	64.32 EUR	1	64.32 EUR
Oth	ners					
	CLEANLINESS INTERIOR					
	Number Code	Description		Unit price	Depr.	Total
	6 I 2 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIO	PR	14.58 EUR		29.16 EUR
	RIM FRONT LEFT					
	Number Code	Description		Unit price	Depr.	Total
	1 I 1 i-vab-herstalu-02	REPAIR ALLOY WHI	EEL	95.00 EUR		95.00 EUR



www.vabfleetservices.be Date: 09/11/2017 4/5

1	2	3	4	5	6	7	8	9	10
95.00	211.80	318.35	63.00	64.32	29.16	0	0	0	0
95.00	105.90	159.18	63.00	64.32	29.16	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
251.48	530.15	0		781.63
HOG: 0	BG: 0		NA Deprec.	516.56
			0.00%	
			TOTAL	516.56



www.vabfleetservices.be Date: 09/11/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : NOT EXECUTED : Reason : Remark :	0 min	Waiting time: 0 m Reason:	iin	Towing time : Reason :	0 min
Prices in EUR with	out VAT				
Authorized by customer :			Executed by VAB Fleet Se	rvices	
Remark authorized cust	omer :				
Date :	09/11/2017	Hour:			
Company:					
Executed by VAB Fleet Services					
E-Mail :	@				
Signature authorized by c	ustomer		+		
×					