

D4GNH5

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	205404 KM
File nr. :	1452317	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
306AVB / VF1KZ0B0641466742 /		yr of constructionr :	/
E-File nr. :		First registration :	03/08/2009
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / MEGANE BREAK	Fuel type :	DIESEL
Object nr. :	65046	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	AGECI VRD SPRL	Co2:	120g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	MEGANE GT Expression 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	106	kW:	78
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	FIRESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	FIRESTONE	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] WINDSCREEN/CENTER/LEFT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR BUMPER/LEFT/LEFT		SCRATCH WITH PAINT DAMAGE		
	Number Code	Description	Unit price	Depr.	Total
6	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE		
	Number Code	Description	Unit price	Depr.	Total
0	0				
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	BONNET/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE	+DEUKEN	
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	BONNET/CENTER/RIGHT		OTHER DAMAGES	ISOLATIE BINNENIN	
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
8	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	BONNET/RIGHT/CENTER		OTHER DAMAGES	RIUTENSPROEIER LEIDING KAPOT	
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
8	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

[x]	FRONT BUMPER/LEFT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	0 EUR		50 %	
3	20 LU =96.00 EUR	0 EUR	235.80 EUR	50 %	331.80 EUR
[x]	REAR DOOR/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR

Interior

[x]	CENTER CONSOLE	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR	0 EUR		50 %	
9	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 6	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	87.48 EUR

HUB CAP FL

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

HUB CAP REAR L

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

HUB CAP FR

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR
Number	Code	Description	Unit price	Depr.	Total
8	1	ISOLATIE	50.00 EUR	50 %	50.00 EUR
Number	Code	Description	Unit price	Depr.	Total
8	1	RUITENSPROEIER LEIDING	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
9	1	ASBAK	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
87.48	120.00	735.00	290.08	211.80	412.32	308.20	152.00	54.00	0
87.48	60.00	367.50	145.04	105.90	261.48	154.10	76.00	27.00	0

INNOVATIVE	TRADITIONAL	GENERAL	
198.12	2172.76	0	2370.88
HOG: 0	BG: 0		NA Deprec. 1284.50
			0.00%
			TOTAL 1284.50

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 11:44 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	