

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	107079 KM
File nr. :	1455725	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FRM191 / WVVZZZAUZEW101143 /		yr of constructionr :	/
E-File nr. :		First registration :	02/10/2013
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	12422	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	OUTDOOR SERVICES SA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GOLF BER Trendline 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] BRIDGESTONE Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	M+S
Rear tyre	195	65	R	15	M+S

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	WINDOW REAR DOOR/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT MUDGUARD/RIGHT/CENTER	DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE			
		Repair paint - LI	New paint - E	Depr.	Total	
6	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	REAR MUDGUARD/LEFT/CENTER	DENT	LAKSCHADE			
		Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	REAR MUDGUARD/RIGHT/REAR	OTHER DAMAGES	SL HERSTELD			
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	FRONT DOOR/LEFT/REAR	DENT	LAKSCHADE			
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR	
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	INWERKING			
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR	
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	ISOLATIE			
		Repair paint - LI	New paint - E	Depr.	Total	
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR	
[x]	FRONT BUMPER/CENTER/LEFT	DENT				
		Repair paint - LI	New paint - E	Depr.	Total	
2	20 LU =96.00 EUR	0 EUR	235.80 EUR	50 %	331.80 EUR	

Interior

[x]	FLOOR FL		CUT / TORN		
		Repair paint - LI	New paint - E	Depr.	Total
1	40 LU =192.00 EUR	0 EUR		50 %	192.00 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	CARPET	60.00 EUR	50 %	60.00 EUR
2	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR
1	1	ISOLATIE	50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
326.00	735.00	290.08	318.35	308.20	211.80	95.00	0	0	0
163.00	367.50	145.04	159.18	154.10	105.90	95.00	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	2189.43	0	2284.43
HOG: 0	BG: 0		NA Deprec. 1189.72
			0.00%
			TOTAL 1189.72

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/11/2017 Hour : 13:01 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	