

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	60490 KM
File nr. :	1450656	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FCW659 / VF1JZ14P648909895 /		yr of constructionr :	/
E-File nr. :		First registration :	28/05/2013
VFS-nr. :		Color :	SILVER
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.SCENIC Energ.Expression 7pl.FAP 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1461
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
	[x]								

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	+ DEEL TE POL.
[x]	REAR DOOR/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT	
[x]	REAR DOOR/LEFT/FRONT	DENT	
[x]	FRONT DOOR/LEFT/REAR	DENT	
[x]	FRONT DOOR/RIGHT/CENTER	DENT	+POL.
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS	

Interior

[x]	BOOT LID IN	SCRATCHED
-----	-------------	-----------

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	-------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	10 LU =48.00 EUR	318.35 EUR		50 %	366.35 EUR

Others

	HUB CAP FR				
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
30.00	366.35	0	0	0	0	0	0	0	0
15.00	183.18	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	396.35	0	396.35
HOG: 0	BG: 0		NA Deprec. 198.18
			0.00%
			TOTAL 198.18

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 02/11/2017 Hour : 13:04 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	