

www.vabfleetservices.be Date: 07/11/2017 1/5

D66O46

## [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner:		Mileage :	84224 KM
File nr. :	1453701	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LKF589 / WVWZZZAUZFW	V323298 /	yr of constructionr :	/
E-File nr. :		First registration :	12/10/2015
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	59063	Fuel:	
Classification:	E	Environment Class:	EURO 5
Customer company:	VAB RIJSCHOOL NV	Co2:	98g/km
Driver :		Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
нр:	90	kW:	66
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Driving school (previously)
General condition:			



www.vabfleetservices.be Date: 07/11/2017 2/5

Original registr. number :	OK		Service manual :	NOK	[x] MISSING/INCOMPLETE
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

### Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		Hubcap:	
Wheel RL:	[x]	CONTINENTAL	Tyre:		OK	[x]	4-6 /	Rim:		Hubcap:	
Wheel FR:	[x]	CONTINENTAL	Tyre:	[x]	OK	[x]	2-4 /	Rim:		Hubcap: [x]	SCRATCHED
Wheel RR:	[x]	CONTINENTAL	Tyre:		OK	[x]	4-6 /	Rim:		Hubcap: [x]	SCRATCHED
Wheel RES:	[x]	CONTINENTAL	Tyre:		OK	[x]	>6/	Rim:		Hubcap:	
l		[x] W	idth			He	ight		Туре	Rim	Index
			105						_		

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	Н
Rear tyre	195	65	R	15	Н

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



4 0 LU =0.00 EUR

# **APPRAISAL**

07/11/2017 Date: www.vabfleetservices.be 3/5

<b>D</b> -	dunica de VO codo do coo					
ВО	dywork \& windows					
[x]	REAR MUDGUARD/RIGHT/FRONT		DENT			
x]	ROOF/CENTER/LEFT		DENT			
x]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAINT	DAMAGE		
x]	BONNET/CENTER/LEFT		DENT			
x]	BONNET/CENTER/RIGHT		DENT			
x]	FRONT MUDGUARD/RIGHT/FRONT		SCRATCH (WITHOUT P	AINT DAMAGE	)	
٩c	cessories and others					
[x]	VEH COVERED WITH STICKERS		STICKER(S)			
ST	ATUS: NOT ACCEPTAB	LE				
30	dywork \& windows					
x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT	`DAMAGE		
x]	REAR BUMPER/CENTER/LEFT	Repair paint - LI	SCRATCH WITH PAINT  New paint - E	`DAMAGE	Depr.	Total
x]	REAR BUMPER/CENTER/LEFT  3 0 LU =0.00 EUR	Repair paint - LI 211.80 EUR		`DAMAGE	Depr. 50 %	
				DAMAGE	-	Total 211.80 EUR
	3 0 LU =0.00 EUR		New paint - E	DAMAGE Unit price	50 %	
	3 0 LU =0.00 EUR WINDSCREEN/CENTER/LEFT	211.80 EUR	New paint - E		50 % 2X	211.80 EUR
	3 0 LU =0.00 EUR  WINDSCREEN/CENTER/LEFT  Number Code	211.80 EUR  Description	New paint - E	Unit price	50 % 2X	211.80 EUR Total
	3 0 LU =0.00 EUR  WINDSCREEN/CENTER/LEFT  Number Code  6 I 1 i-vab-herstr-01	211.80 EUR  Description  WINDOW REPAIR	New paint - E WINDOW DAMAGE	Unit price 58.80 EUR	50 % 2X Depr.	211.80 EUR  Total  58.80 EUR
[x]	3 0 LU =0.00 EUR  WINDSCREEN/CENTER/LEFT  Number Code  6 I 1 i-vab-herstr-01  Number Code	211.80 EUR  Description  WINDOW REPAIR  Description	New paint - E WINDOW DAMAGE	Unit price 58.80 EUR Unit price 29.40 EUR	50 % 2X Depr.	211.80 EUR  Total  58.80 EUR  Total
x]	3 0 LU =0.00 EUR  WINDSCREEN/CENTER/LEFT  Number Code  6 I 1 i-vab-herstr-01  Number Code  6 I 1 i-vab-herstr-02	211.80 EUR  Description  WINDOW REPAIR  Description	New paint - E  WINDOW DAMAGE  PAIR	Unit price 58.80 EUR Unit price 29.40 EUR	50 % 2X Depr.	211.80 EUR  Total  58.80 EUR  Total
x]	3 0 LU =0.00 EUR  WINDSCREEN/CENTER/LEFT  Number Code  6 I 1 i-vab-herstr-01  Number Code  6 I 1 i-vab-herstr-02	211.80 EUR  Description  WINDOW REPAIR  Description  SUPPL WINDOW REP	New paint - E  WINDOW DAMAGE  PAIR  SCRATCH WITH PAINT	Unit price 58.80 EUR Unit price 29.40 EUR	50 % 2X Depr. Depr.	211.80 EUR  Total  58.80 EUR  Total  29.40 EUR
x]	3 0 LU =0.00 EUR  WINDSCREEN/CENTER/LEFT  Number Code  6 I 1 i-vab-herstr-01  Number Code  6 I 1 i-vab-herstr-02  FRONT BUMPER/LEFT/CORNER	Description WINDOW REPAIR Description SUPPL WINDOW REF	New paint - E  WINDOW DAMAGE  PAIR  SCRATCH WITH PAINT	Unit price 58.80 EUR Unit price 29.40 EUR	50 %  2X  Depr.  Depr.	Total  58.80 EUR  Total  29.40 EUR
[x] [x] Ac	3 0 LU =0.00 EUR  WINDSCREEN/CENTER/LEFT  Number Code  6 I 1 i-vab-herstr-01  Number Code  6 I 1 i-vab-herstr-02  FRONT BUMPER/LEFT/CORNER	Description WINDOW REPAIR Description SUPPL WINDOW REF	New paint - E  WINDOW DAMAGE  PAIR  SCRATCH WITH PAINT	Unit price 58.80 EUR Unit price 29.40 EUR DAMAGE	50 %  2X  Depr.  Depr.	Total  58.80 EUR  Total  29.40 EUR

75.00 EUR

50 %

75.00 EUR



www.vabfleetservices.be Date: 07/11/2017 4/5

	Others
•	

CLEANLINESS INTERIOR

Number Code Description Unit price Depr. Total

I 2 specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR 14.58 EUR 29.16 EUR

HUB CAP FR

Repair paint - LI New paint - E Depr. Total 5 0 LU =0.00 EUR

#### Pieces

	Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP		30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
29.16	211.80	211.80	75.00	30.00	88.20	0	0	0	0
29.16	105.90	105.90	37.50	15.00	88.20	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
645.96		0	528.60	117.36
381.66	NA Deprec.		BG: 0	HOG: 0
	0.00%	-		
381.66	TOTAL			



07/11/2017 Date: www.vabfleetservices.be 5/5

[x] = Status Modification

**Pictures:** No

CIRCUM	STANCES		UNDER CONDITION - VEHICLE WET				
Extra Time :	0 min	Waiting time : 0 Reason :	min	Towing time : Reason :	0 min		
NOT EXECUTED Reason:	D: No	•		•			
Remark:							
Prices in EUR	without VAT						
Authorized by customer :			Executed by VA	B Fleet Services			
Remark authorize	ed customer :						
Date :	07/11/2017	<b>Hour:</b> 12:05					
Company :							
Executed by VAB Services	Fleet						
E-Mail :	@						
Signature authorize	ed by customer						
2							