

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	99092 KM
File nr. :	1453797	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1BBK503 / VF1FW1AF545245329 /		yr of constructionr :	/
E-File nr. :		First registration :	26/04/2011
VFS-nr. :		Color :	WHITE
Make + Model :	RENAULT / KANGOO EXPRESS	Fuel type :	DIESEL
Object nr. :	47822	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	VEOLIA SA/NV	Co2:	140g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	KANGOO Expr.COMPACT Gr.Confort 68PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1461
Gear box :	Manueel	Number of places:	2
Number of gears:	5	Number of doors:	4
HP:	68	kW:	50
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	>6/	Rim :	[x]	BROKEN DOWN / DAMAGED	/	Hubcap :
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	185	70	R	14	T
Rear tyre	185	70	R	14	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	DENT
[x]	BONNET/CENTER/LEFT	DENT
[x]	BONNET/CENTER/RIGHT	DENT
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT/RIGHT	SCRATCH WITH PAINT DAMAGE

Interior

[x]	STEERING WHEEL	OTHER DAMAGES
[x]	BOOT LID IN	OTHER DAMAGES

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
-----	---------------------------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
5	15 LU =72.00 EUR		0 EUR		50 %
					72.00 EUR
[x]	REAR DOOR/CENTER/LEFT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
6	0 LU =0.00 EUR		226.26 EUR		50 %
					226.26 EUR
[x]	REAR MUDGUARD/LEFT/CENTER	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
4	0 LU =0.00 EUR		231.15 EUR		50 %
					231.15 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
7	20 LU =96.00 EUR		231.15 EUR		50 %
					327.15 EUR

[x]	ROOF/REAR/LEFT		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
8	10 LU =48.00 EUR	361.13 EUR		50 %	409.13 EUR	
[x]	WINDSCREEN/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
2	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR	
[x]	FRONT BUMPER/LEFT/CORNER		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
3	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR	

Interior

[x]	DASHBOARD		CARVED			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR
[x]	CARPET FL		CUT / TORN			
		Repair paint - LI	New paint - E	Depr.	Total	
1	40 LU =192.00 EUR	0 EUR		50 %	192.00 EUR	
[x]	SEAT FL		CUT / TORN			
		Repair paint - LI	New paint - E	Depr.	Total	
1	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR	

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE		BROKEN / CRACKED			
		Repair paint - LI	New paint - E	Depr.	Total	
9	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR	
[x]	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
10	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SEAT UPHOLSTERY TISSUE	90.00 EUR	50 %	90.00 EUR
1	1	CARPET	45.00 EUR	50 %	45.00 EUR
2	1	WIND SCREEN	275.40 EUR	50 %	275.40 EUR
3	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
5	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR
9	1	MIRROR	90.00 EUR	50 %	90.00 EUR
10	1	MIRROR	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
557.64	395.40	398.40	231.15	329.40	226.26	327.15	409.13	138.00	138.00
334.14	197.70	199.20	115.58	164.70	113.13	163.58	204.56	69.00	69.00

INNOVATIVE	TRADITIONAL	GENERAL	
110.64	3039.89	0	3150.53
HOG: 0	BG: 3		NA Deprec. 1630.58
			0.00%
			TOTAL 1630.58

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 09:10 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	