

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	73294 KM
<b>File nr. :</b>	1444100	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FQF730 / VF17R040H49260799 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	23/09/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	RENAULT / CLIO	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	EGEMIN CONSULTING NV	<b>Co2:</b>	95g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	CLIO IV BRE Expression 75PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	1461
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	75	<b>kW:</b>	55
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL: [x] GOODYEAR Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] GOODYEAR Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] GOODYEAR Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RR : [x] GOODYEAR Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] GOODYEAR Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	185	65	R	15	H
Rear tyre	185	65	R	15	H

Remark :

## Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT/FRONT	DENT

### Interior

[x]	SEAT FL	STAIN
[x]	SEAT FR	STAIN
[x]	SEAT REAR L	STAIN
[x]	SEAT REAR RIGHT	STAIN

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
		<b>Total</b>		
	2 0 LU =0.00 EUR	246.56 EUR		50 %
				246.56 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT		LAKSCHADE
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
		<b>Total</b>		
	3 0 LU =0.00 EUR	246.56 EUR		50 %
				246.56 EUR
[x]	REAR DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
		<b>Total</b>		
	2 5 LU =24.00 EUR	254.68 EUR		50 %
				278.68 EUR
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
		<b>Total</b>		
	3 0 LU =0.00 EUR	254.68 EUR		50 %
				254.68 EUR
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
		<b>Total</b>		
	3 0 LU =0.00 EUR	254.68 EUR		50 %
				254.68 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
		<b>Total</b>		
	1 0 LU =0.00 EUR	169.44 EUR		50 %
				169.44 EUR

1	2	3	4	5	6	7	8	9	10
169.44	525.24	755.92	0	0	0	0	0	0	0
84.72	262.62	377.96	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1450.60	0	<b>1450.60</b>
HOG: 0	BG: 1		NA Deprec. 725.30
			0.00%
			<b>TOTAL 725.30</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - DARK

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 30/10/2017 <b>Hour :</b> 09:14 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	