

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	136397 KM
File nr. :	1453342	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
UZ8272 / WVWZZZ3CZDE123392 /		yr of constructionr :	/
E-File nr. :		First registration :	23/04/2013
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / PASSAT	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	PRESENCE SARL	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PASSAT VAR Comfortline 140PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio :
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle :
Jack, wheelspanner :	Oil level :
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/RIGHT/CENTER DENT
- [x] FRONT DOOR/RIGHT/CENTER DENT
- [x] BONNET/CENTER/LEFT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR DOOR/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
4	25 LU =120.00 EUR	0 EUR	237.22 EUR	50 %	357.22 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	CHROOM LIJST	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	FENDER FR	172.80 EUR	50 %	172.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	241.80	301.68	530.02	0	0	0	0	0	0
105.90	120.90	150.84	265.01	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1285.30	0	1285.30
HOG: 0	BG: 0		NA Deprec. 642.65
			0.00%
			TOTAL 642.65

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/11/2017 Hour : 15:22 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	